

# **Alachua County**

## **ADA Transition Plan**

November 2024

### **Transition Plan Table of Contents**

#### **Facilities**

1.	Admin Annex5
2.	State Attorney Building10
3.	Civil Courthouse
4.	Wilson Building
5.	Admin Building60
6.	Main Street Legal
7.	34 <sup>th</sup> Tag Agency73
8.	Criminal Justice Center
9.	Hazardous Waste
10	Health Department State
11	Health Department County82
12	. JT Walls
13	Metamorphosis
14	Admin Transfer Station
15	Records Retention
16	Animal Services
17	Recycling Transfer Station98
18	Public Defender
19	SWAG Resource Center 102
20	Work Release 105
21	. Canterbury Equine Center 108

#### **Critical Facilities**

22.	Consolidated Communication Center1	20
23.	Sheriff's Office1	.23
24.	Fire Station HQ1	.25
25.	Public Works Warehouse1	.28
26.	Public Works Fleet Building1	.32
27.	Public Works Main Building1	.36
28.	Alachua County Jail 1	.42
29.	Fire Station 201	.46
30.	Fire Station 231	.48
31.	Fire Station 241	.53
32.	Fire Station 251	.55
33.	Fire Station 301	57
34.	Fire Station 331	.59
35.	Fire Station 401	61
36.	Fire Station 41 1	.62
37.	Fire Station 601	.63
38.	Fire Station 801	.67
39.	Fire Station 81 1	.71
40.	Fire Station 821	.73

#### <u>Parks</u>

41.	Copeland Park	176
42.	Cynthia Moore Chestnut Park	179
43.	Earl P. Powers Park	181
44.	Kanapaha Botanical Gardens	184
45.	Jonesville Rotary Park	187
46.	Santa Fe Lake Park	190
47.	Lochloosa Park	19 <b>2</b>
48.	Marjorie K. Rawlings Park	195
49.	Monteocha Park	199
50.	Veterans Memorial Park	201
51.	Owen-Illinois Park	203
52.	Poe Springs	205

### **ADA Transition Plan**

Facility	Admin Annex	Date <u>5/24/2018</u>
Contact Per	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone <u>352-384-3190</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor Lobby Restroom	Water closet doesn't have 60" clearance from the side wall.	Move lavatory left.	Carl Johns	Growth Management schedule to move out FY 2025	14-33-13 14-34-48 14-34-48	TBD	
1 <sup>st</sup> Floor Zoning Office door.	Door needs to be smooth surface on bottom 10".	Replace Door.	Carl Johns	May be more than 5 Ibs force to open door.	14-36-46	TBD	
1 <sup>st</sup> Floor Hallway door	Door doesn't have 18" maneuvering clearance on pull side.	Remove door, widen hallway, or add door opener.	Carl Johns	Moving to new building 2024		TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor Right- side Restroom	Door less than 32" wide, No rear grab bar, lavatory not accessible, toilet paper too close to water closet.	Install 32" wide door, remodel restroom.	Carl Johns	Moving to new building 2024	15-01-58 15-02-07 15-02-25	TBD	
1 <sup>st</sup> Floor Left- Side Restroom	Door is less than 32" wide, No grab bars, lavatory not accessible, Toilet paper dispenser behind water closet, inadequate clearances.	Install 32" wide door. Remodel restroom	Carl Johns	Moving to new building 2024	15-12-27 15-12-34	TBD	
1 <sup>st</sup> Floor Elevator Door	Up/down indicator lights not on lobby side	Move lights	Carl Johns	Moving to new building 2024		TBD	
2 <sup>nd</sup> Floor Left- Side Restroom Door	Door is narrower than 32"	Replace door	Carl Johns	Moving to new building 2024		TBD	
2 <sup>nd</sup> Floor Left- Side Restroom	Inadequate clearance around water closet, door too narrow	Remodel restroom.	Carl Johns	Moving to new building 2024	15-39-15 15-39-22 15-40-22 15-45-24	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor Right- Side Restroom Door	Water fountain blocking maneuvering clearance, sign mounted on door	Move water fountain, move sign to wall, latch side of door.	Carl Johns	Moving to new building 2024	15-49-14	TBD	
2 <sup>nd</sup> Floor Right- Side Restroom	Door narrower than 32", inadequate clearance around water closet, lavatory not accessible	Remodel restroom	Carl Johns	Moving to new building 2024	15-50-37 15-50-56 15-51-05 15-51-11	TBD	
Conference Room 207 Door	Door knob requires gripping and twisting wrist	Replace with accessible handle.	Carl Johns		16-02-20	TBD	
3 <sup>rd</sup> Floor Left- Side Restroom Door.	Less than 32" wide.	Replace door.	Carl Johns	Moving to new building 2024	16-06-45	TBD	
3 <sup>rd</sup> Floor Right- Side Restroom Door	Less than 32" wide, less than 18" maneuvering clearance	Replace door, move obstructions	Carl Johns	Moving to new building 2024	16-09-04	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
3 <sup>rd</sup> Floor Right- Side Restroom	Inadequate clearance around water closet, lavatory not accessible	Remodel restroom	Carl Johns	Moving to new building 2024	16-11-03 16-11-11 16-11-15 16-11-21 16-16-53	TBD	
3 <sup>rd</sup> Floor Left- Side Restroom	Inadequate clearance around water closet, lavatory not accessible.	Remodel restroom	Carl Johns	Moving to new building 2024	16-17-25 16-20-46 16-20-51 16-21-40	TBD	
West Stairway Exterior Door	Not 18" maneuvering clearance on latch side of door.	Install push button door opener on inside.	Carl Johns	Moving to new building 2024		TBD	
West Exterior Path and Ramp.	Landing outside stairway door not level, handrail doesn't extend past end of ramp, pathway not level	Regrade path, replace handrail	Carl Johns	Moving to new building 2024	15-48-43 15-49-57 15-31-39 15-51-55 15-54-11	TBD	
East Stairway 3 <sup>rd</sup> Floor Door	Door knob requires gripping and twisting, gap in floor threshold	Fix threshold, replace with accessible handle. Repair floor.	Carl Johns	Moving to new building 2024	16-10-11 16-10-26	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
West Stairway 2 <sup>nd</sup> Floor Door	Door knob requires gripping and twisting, floor damaged.	Repair floor, replace with accessible handle	Carl Johns	Moving to new building 2024	16-16-12	TBD	
West Stairway Handrails	Handrails are 2x4's on inside	Replace handrails	Carl Johns	Moving to new building 2024	16-18-23 16-20-40	TBD	
Main entrance	Inadequate tread depth for steps.	Add handrails for steps.	Carl Johns	Moving to new building 2024	16-24-21 16-24-28	TBD	

### **ADA Transition Plan**

Facility	State Attorney Building	Date <u>9/12/2018</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone 3

352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
3 <sup>rd</sup> Floor North East Stairs Door	Handle requires gripping and twisting of wrist. Requires more than 5 lbs to open.	Adjust or replace door closer. Replace with accessible handle.	Carl Johns		14_52_22 14_52_47	Complete
3 <sup>rd</sup> Floor Men's Restroom	Inadequate turning space, mirror mounted at 50", Sink and faucet not accessible.	Requires remodeling.	Carl Johns		15_03_06 15_03_11 15_03_21 15_13_58 15_16_19	FY 2026
3 <sup>rd</sup> Floor Men's Restroom Door	Door and hallway too narrow for compliance.	Requires remodeling.	Carl Johns		15_03_06 15_07_33	FY 2026

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
3 <sup>rd</sup> Floor Men's Restroom Stall	Stall too small, door swings inward, no grab bars, flush control on closed- side, door not self- closing.	Requires remodeling.	Carl Johns	No other accessible stalls.	15_13_58	FY 2026	
3 <sup>rd</sup> Floor Women's Restroom Vestibule Outer Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		15_26_19	Complete	
3 <sup>rd</sup> Floor Women's Restroom Vestibule Inner Door	Inadequate push- side clearance.	Move furniture to create 48" clearance.	Carl Johns		15_31_06	Complete	
3 <sup>rd</sup> Floor Women's Restroom	Inadequate turning space, mirror mounted at 50", sink is not accessible	Requires remodeling.	Carl Johns		15_35_01	FY 2026	
3 <sup>rd</sup> Floor Women's Restroom Stalls	Door swings inward, not enough space, no grab bars,	Requires remodeling.	Carl Johns		15_37_53 15_41_50	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor North West Left-Side Restroom Door	Door closes in less than 5 seconds. Handle requires gripping and twisting.	Adjust or replace door closer. Replace handle with accessible handle.	Carl Johns		1206 1214	Complete	
1 <sup>st</sup> Floor North West Men's Restroom Door	Door closes in less than 5 seconds. Handle requires gripping and twisting.	Adjust or replace door closer. Replace handle with accessible handle.	Carl Johns		1214	Complete	
1 <sup>st</sup> Floor North West Women's Restroom	Coat hook mounted 73" high, sink not accessible, pipes are not covered.	Replace sink, move coat hooks to 48", install insulation on pipes.	Carl Johns		1209	July 2025	
1 <sup>st</sup> Floor Lobby Unisex Accessible Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		16_38_37 16_38_51 16_39_01	Complete	
1 <sup>st</sup> Floor Lobby Unisex Accessible Restroom	Mirror mounted 40.5″ high.	Move mirror to 40".	Carl Johns		16_38_51	July 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor Lobby Women's Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		16_39_49	Complete	
1 <sup>st</sup> Floor Lobby Women's Restroom	Inadequate turning space. Paper towel dispenser mounted at 50". Flush controls on closed side.	Requires renovation. Move paper towel dispenser to 48". Change flusher for open side flusher.	Carl Johns		16_40_05 16_40_19 16_40_34	FY 2026	
2 <sup>nd</sup> Floor North East Stairs Door	Handle requires gripping and twisting wrist.	Replace hardware with accessible handle.	Carl Johns		111928	July 2025	
2 <sup>nd</sup> Floor Men's Restroom	Inadequate turning space. Mirror mounted at 50", paper towel dispenser 53". Sink not accessible.	Requires remodeling. Move mirror to 40", paper towel dispenser to 48". Replace sink w/ accessible sink.	Carl Johns		112001 112004	FY 2026	
2 <sup>nd</sup> Floor Men's Restroom Stall	Not enough space. No Grab Bars.	Requires remodeling. Install grab bars.	Carl Johns		112013	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor Women's Restroom Vestibule Outer Door	Closes in less than 5 seconds. Less than 48" clearance on push-side of door.	Adjust or replace door closer. Move furniture to make clearance.	Carl Johns		111935	Complete	
2 <sup>nd</sup> Floor Women's Restroom	Inadequate turning space, paper towels mounted at 50″.	Requires remodel, mount paper towels at 48".	Carl Johns		112120	FY 2026	
2 <sup>nd</sup> Floor Women's Restroom Stalls	Door swings inward, not enough space, no grab bars, flush controls on closed side.	Requires remodeling. Install grab bars, replace flush controls.	Carl Johns		112127 112130 112134	FY 2026	
Main Entrance Door	Bottom 10" of door not smooth.	Replace door.	Carl Johns		89 90 91	Aug 2025	
Main Entrance Vestibule Inner Door	Bottom 10" of door not smooth.	Replace door.	Carl Johns		113705	Aug 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor Lobby Door	Closes in less than 5 seconds, requires more than 5 lbs to open. Hardware not accessible.	Adjust or replace door closer. Replace hardware with accessible handle.	Carl Johns	Keycard reader security door.	94 95 96	Complete	
1 <sup>st</sup> Floor North East Men's Restroom Door	Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		1210	Complete	
3 <sup>rd</sup> Floor South Stairs Door	Closes in less than 5 seconds, requires more than 5 lbs to open. Hardware requires gripping and twisting of wrist.	Adjust or replace door closer. Replace hardware with accessible handles.	Carl Johns		100	Complete	
1 <sup>st</sup> Floor North East Men's Restroom	Inadequate turning space, no grab bars. Flush control on closed side. Faucet not accessible.	Requires remodel, add grab bars, replace flush control with open- side. Replace faucet.	Carl Johns		1211	Aug 2025	
1 <sup>st</sup> Floor North East Women's Restroom	Inadequate turning space. Toilet seat 16" tall. No grab bars.	Requires remodeling. Replace faucet, install grab bars.	Carl Johns		1213	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor Central Stairs Door	Closes in less than 5 seconds, requires more than 5 lbs of force.	Adjust or replace door closer.	Carl Johns		111859	Complete	
3 <sup>rd</sup> Floor South Stairs	No outer Handrail	Install outer handrail.	Carl Johns		101 102	Aug 2025	
2 <sup>nd</sup> Floor South Stairs Door	Closes in less than 5 seconds, requires more than 5 ls of force to open.	Adjust or replace door closer.	Carl Johns		103	Complete	
3 <sup>rd</sup> Floor Lobby Door	Door closes in less than 5 seconds. Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns	Keycard reader security door.	97	Complete	
3 <sup>rd</sup> Floor South East Restroom	Inadequate turning space.	Requires remodeling.	Carl Johns		113116 113121 113133	FY 2026	

### **ADA Transition Plan**

Facility	Civil Courthouse	Date <u>4/28/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email fjohns@alachuacounty.us

Phone 352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Main Entrance Walkway	Handrails are too large to grip around, and are 29″ tall.	Replace with graspable handrails that are 34-38" tall.	Carl Johns		14_39_50 14_40_24	Oct 2025	
Main Entrance Doors	Requires more than 5 lbs to open. Lower 10" not smooth.	Adjust or replace door closers. Replace doors.	Carl Johns		14_42_36 14_42_52 14_48_14 14_48_34	Complete	
1 <sup>st</sup> Floor Men's Restroom Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		15_03_47	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor Men's Restroom	Mirror mounted at 44.5". Accessible stall door not self- closing.	Move mirror to 40". Install stall-door closer.	Carl Johns		15_07_25 15_07_28 15_07_33 15_07_40 15_07_46 15_07_49	Oct 2025	
1 <sup>st</sup> Floor Lobby Water Fountains	Water flow 3" from fountain front.	Adjust so flow is 4" from front.	Carl Johns		15_25_55 15_26_08	Complete	
1 <sup>st</sup> Floor Women's Restroom Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		15_32_04	Complete	
1 <sup>st</sup> Floor Women's Restroom	Coat Hooks mounted higher than 48". Accessible stall door not self- closing.	Move coat hook to 48". Install stall- door closer.	Carl Johns		15_44_47 15_44_54 15_44_59 15_45_05	Oct 2025	
1 <sup>st</sup> Floor Traffic Lobby West Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns			Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
4 <sup>th</sup> Floor Lobby Men's Restroom Door	Door closes in less than 5 seconds. Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns			Complete	
4 <sup>th</sup> Floor Lobby Men's Restroom	Mirror mounted 44" high. Coat hooks mounted at 63". Accessible stall door not self- closing.	Move mirror to 40", coat hooks to 48". Install stall door- closer.	Carl Johns			Oct 2025	
4 <sup>th</sup> Floor Lobby Women's Restroom Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns			Complete	
4 <sup>th</sup> Floor Lobby Women's Restroom	Coat hooks mounted at 63" high. Accessible stall door not self- closing.	Move coat hooks to 48". Install stall door closer.	Carl Johns			Oct 2025	
4 <sup>th</sup> Floor Lobby Water Fountains	Water flow must be 4" tall.	Adjust water fountain.	Carl Johns			Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
3 <sup>rd</sup> Floor Lobby Men's Restroom Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns			Complete	
3 <sup>rd</sup> Floor Lobby Men's Restroom	Accessible stall door not self-closing.	Install stall door closer.	Carl Johns		100622 100624 100628 100632 100819	Oct 2025	
3 <sup>rd</sup> Floor Lobby Women's Restroom Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		101914 101918	Complete	
3 <sup>rd</sup> Floor Lobby Women's Restroom	Coat hooks mounted 62" high.	Move to 48".	Carl Johns		101835 101837 101839 101914 101918	Oct 2025	
2 <sup>nd</sup> Floor Men's Lobby Restroom Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		102746	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor Men's Restroom	Coat hooks mounted at 62" high. Accessible stall door not self- closing.	Move coat hooks to 62". Install stall door closer.	Carl Johns		102937 102939 102942 103100 103104	Oct 2025	
2 <sup>nd</sup> Floor Lobby Women's Restroom Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		103556	Complete	
2 <sup>nd</sup> Floor Lobby Women's Restroom	Coat hooks mounted 62" high. Accessible stall door not self- closing.	Move coat hooks to 48". Install stall door closers.	Carl Johns		103828	Oct 2025	
Judge Restroom	Mirror and paper towel dispenser mounted at 60" high. Door not self- closing.	Move mirror to 40". Move paper towels to 48". Install door closer.	Carl Johns	4 <sup>th</sup> floor judge restroom?		Oct 2025	
4 <sup>th</sup> Floor South East Judge Office – South Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns	409	93952	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
4 <sup>th</sup> Floor South Stairs Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		94257	Complete	
4 <sup>th</sup> Floor South West Judge Office – South Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns	408	94716	Complete	
4 <sup>th</sup> Floor South East Judge Office – North Door	Requires more than 5 lbs to open. 16" of maneuvering clearance on latch side.	Adjust or replace door closer. Create 18" maneuvering clearance.	Carl Johns		95159	Complete	
4 <sup>th</sup> Floor South West Judge Office – North Door	Requires more than 5 lbs to open. Closes faster than 5 seconds. 17" maneuvering clearance on latch side.	Adjust or replace door closer. Create 18" maneuvering clearance on latch side of the door.	Carl Johns	410	95236	Complete	
4 <sup>th</sup> Floor Chief Judge Conference Room Outer Vestibule Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closers.	Carl Johns	412	95800	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
4 <sup>th</sup> Floor Chief Judge Conference Room Inner Vestibule Door	Requires more than 5 lbs to open.	Adjust or replace door closers.	Carl Johns		100028	Complete	
4 <sup>th</sup> Floor Chief Judge Conference Room Restroom Door	16" maneuvering space on latch side of door.	Create 18" clearance.	Carl Johns		100409 100418 100421 100430	Oct 2025	
4 <sup>th</sup> Floor Law Library Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns	413	101446	Complete	
Courtroom 4A Door.	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		101550	Complete	
Personnel ADA Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns	414A	102312 102348	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
4 <sup>th</sup> Floor North West Judge's Office Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns	415	102902	Complete	
4 <sup>th</sup> Floor North Glass Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		103308	Complete	
4 <sup>th</sup> Floor North Stairs Door	Requires more than 5 lbs to open	Adjust or replace door closer	Carl Johns		103536	Complete	
4 <sup>th</sup> Floor North East Judge's Office	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns	416	103913	Complete	
4 <sup>th</sup> Floor North East Judge's Conference Room Door	Handle requires gripping and twisting wrist.	Replace with accessible handle.	Carl Johns		104315	Oct 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 4A Jury Door	54" clearance on pull-side.	Create 60" clearance on pull-side.	Carl Johns		104735	Oct 2025	
Courtroom 4A Jury Left- Restroom	Coat hooks mounted 60" high.	Move to 48".	Carl Johns		105112 105139 105143 105144	Oct 2025	
Courtroom 4A Jury Right- Restroom Door	Handle requires gripping and twisting wrist.	Replace with accessible hardware.	Carl Johns			Oct 2025	
Courtroom 4A Jury Right- Restroom	Door swings in. Not enough floor space. Paper towels mounted at 54". Mirror at 49". Sink not accessible.	Requires remodel. Move mirror to 40", paper towels to 48". Replace sink.	Carl Johns	Requires remodeling to make accessible, restroom directly next to it is accessible.	105638 105429 105431 105638	FY 2026	
Courtroom 4A Jury Conference Door	Handle requires gripping and twisting wrist.	Replace hardware with accessible handle.	Carl Johns		110215	Oct 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
4 <sup>th</sup> Floor South East Judge's Office Conference Door	Handle requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		110820	Oct 2025	
4 <sup>th</sup> Floor South West Judge Conference Room	Handle requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		111029	Oct 2025	
4 <sup>th</sup> Floor North West Judge Office Door	Handle requires gripping and twisting.	Replace hardware wit accessible handle.	Carl Johns		111402	Oct 2025	
Courtroom 3A Main Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		111802	Complete	
Courtroom 3A Jury Door	2" maneuvering clearance on latch side. Hardware requires gripping and twisting.	Replace hardware with accessible handle. Remodel to create 18" clearance or add door opener.	Carl Johns		11219	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 3A Jury Conference Door	Handle requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		112347	Nov 2025	
Courtroom 3A Jury Conference Room Water Fountain	Water flow is 3" tall.	Adjust so water flow is 4" tall.	Carl Johns		112527	Complete	
Courtroom 3A Jury Left- Restroom Door	Handle requires gripping and twisting. 17" clearance on latch- side. 35" clearance on pull-side.	Replace hardware with accessible handle. Requires remodeling for 18" latch clearance, and 60" pull-side.	Carl Johns		112804	Nov 2025	
Courtroom 3A Jury Left- Restroom	Inadequate turning space, door swings into floor space, mirror mounted at 49", 35" depth sink free space.	Requires remodeling. Move mirror to 40".	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	112945 112948	FY 2026	
Courtroom 3A Jury Right- Restroom Door	Handle requires gripping and twisting. 17.5" clearance on latch- side. 35" clearance on pull-side.	Replace hardware with accessible handle. Requires remodeling to create 18" latch clearance & 60" pull-side.	Carl Johns		113222	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 3A Jury Right- Restroom	Inadequate turning space, door swings into floor space, mirror mounted at 49", 35" depth sink free space.	Requires remodeling. Move mirror to 40".	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	113229 113231	TBD	
3 <sup>rd</sup> Floor North West Judge Office Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		113952	Complete	
3 <sup>rd</sup> Floor North West Judge Office Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle	Carl Johns		114031	Nov 2025	
3 <sup>rd</sup> Floor North Glass Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		114402	Complete	
3 <sup>rd</sup> Floor North Stairs Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		114945	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 3B Main Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		115403	Complete	
Courtroom 3B Jury Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		11_56_31	Nov 2025	
Courtroom 3B Jury Conference Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		11_57_13	Nov 2025	
Courtroom 3B Jury Left- Restroom Door	Hardware requires gripping and twisting. 17.5" latch-side clearance, 36" pull- side.	Replace hardware with accessible handle. Requires remodeling to create 18" latch clearance & 60" pull-side clearance.	Carl Johns		11_57_58	FY 2026	
Courtroom 3B Jury Left- Restroom Pt. 1	Inadequate turning space, door swings into floor space, mirror mounted 49" high, 36" depth sink clear space.	Requires remodeling to create space. Move mirror to 40".	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	11_57_31 11_57_34 121554	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 3B Jury Left- Restroom Pt. 2	Water closet centerline 14" from side wall. No grab bars.	Move water closet to 16-18" from side wall. Install grab bars.	Carl Johns		11_57_31 11_57_34 121554	Nov 2025	
Courtroom 3B Jury Right- Restroom Door	Hardware requires gripping and twisting. 17.5" latch-side clearance, 26" pull- side.	Replace hardware with accessible handle. Requires remodeling to create 18" latch clearance & 60" pull-side clearance.	Carl Johns		11_57_47	Nov 2025	
Courtroom 3B Jury Right- Restroom	Inadequate turning space, door swings into clear space, mirror mounted 49" high. 36" depth clear sink space. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars.	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	11_57_41 11_57_43	FY 2026	
Courtroom 3D Main Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		121902	Complete	
Courtroom 3C Main Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		121907	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 3D Jury Door	Hardware requires gripping and twisting. 3.5" latch- side clearance.	Replace hardware with accessible handle. Requires remodeling to create clearance or install door opener.	Carl Johns		103104	FY 2026	
Courtroom 3D Jury Conference Room Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		103154	Nov 2025	
Courtroom 3D Jury Right- Restroom Door	Hardware requires gripping and twisting. 12" clearance latch- side.	Replace hardware with accessible handle. Requires remodeling to create 18" clearance.	Carl Johns		103208	FY 2026	
Courtroom 3D Jury Left- Restroom Door	Hardware requires gripping and twisting. 16″ latch- side clearance.	Replace hardware with accessible handle. Requires remodeling to create 18" clearance.	Carl Johns		103311	FY 2026	
Courtroom 3D Jury Right- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 49" high, 33" depth sink clearance. No grab bars	Requires remodeling to create space. Move mirror to 40". Install grab bars.	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	103805 103810	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 3D Jury Left- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 49" high, 34" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars.	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	103816 103818	FY 2026	
Courtroom 3C Jury Conference Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		104710	Nov 2025	
Courtroom 3C Jury Door	Hardware requires gripping and twisting. 4" clearance latch- side.	Replace hardware with accessible handle. Requires remodel to create 18" clearance or install door opener.	Carl Johns		104726	FY 2026	
Courtroom 3C Jury Left- Restroom Door	Hardware requires gripping and twisting. 17" latch- side clearance.	Requires remodel to create 18" clearance. Replace hardware with accessible handle.	Carl Johns		104732	FY 2026	
Courtroom 3C Jury Right- Restroom Door	Hardware requires gripping and twisting. 17" latch- side clearance.	Requires remodel to create 18" clearance. Replace hardware with accessible handle.	Carl Johns		104740	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 3C Jury Left- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 49" high, 35" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars.	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	105350 105352	FY 2026	
Courtroom 3C Jury Right- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 49" high, 35" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars.	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	105356 105358	FY 2026	
3 <sup>rd</sup> Floor South East Judge office Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		110040	Complete	
3 <sup>rd</sup> Door South East Judge Conference Room	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		110101	Nov 2025	
3 <sup>rd</sup> Floor South Glass Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		110334	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
3 <sup>rd</sup> Floor South Stairs Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		110508	Complete	
3 <sup>rd</sup> Floor South West Judge Office Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		111007	Complete	
3 <sup>rd</sup> Floor South West Judge Office Door	Requires gripping and twisting to open.	Replace hardware with accessible handle.	Carl Johns		111050	Nov 2025	
Courtroom 2D Jury Conference Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		111811	Nov 2025	
Courtroom 2D Jury Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		111831	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 2D Jury Left- Restroom Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		111839	Nov 2025	
Courtroom 2D Jury Right- Restroom Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		111847	Nov 2025	
Courtroom 2D Jury Left- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 49" high, 33" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars.	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	112257 112304	FY 2026	
Courtroom 2D Jury Right- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 49" high, 34" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars.	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	112313 112315	FY 2026	
Courtroom 2D Main Door	Requires more than 5 lbs of opening force.	Adjust or replace door closer.	Carl Johns		112839	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 2C Main Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		112844	Complete	
Courtroom 2C Jury Conference Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		113555	Nov 2025	
Courtroom 2C Jury Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		113609	Nov 2025	
Courtroom 2C Jury Right- Restroom Door	Hardware requires gripping and twisting. 17.5" latch-side clearance.	Replace hardware with accessible handle. Requires remodeling to create clearance.	Carl Johns		113621	FY 2026	
Courtroom 2C Jury Left- Restroom Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		113630	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 2C Jury Right- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 49" high, 36" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	114115 114120	Nov 2026	
Courtroom 2C Jury Left- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 49" high, 36" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	114140 114145	FY 2026	
Courtroom 2A Main Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		114810	Complete	
Courtroom 2A Jury Conference Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		114951	Nov 2025	
Courtroom 2A Jury Right- Restroom Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		115002	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 2A Jury Left- Restroom Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		115010	Nov 2025	
Courtroom 2A Jury Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		115018	Nov 2025	
Courtroom 2A Jury Right- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 47" high, 36" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	115032 115035	FY 2026	
Courtroom 2A Jury Left- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 48" high, 36" depth sink clearance. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	115041 115043	FY 2026	
Courtroom 2B Main Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		101032	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 2B Jury Conference Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		101234	Nov 2025	
Courtroom 2B Jury Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		101251	Nov 2025	
Courtroom 2B Jury Left- Restroom Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		101301	Nov 2025	
Courtroom 2B Jury Right- Restroom Door	Hardware requires gripping and twisting. 16" clearance on latch- side.	Replace hardware with accessible handle. Requires remodeling for 18" clearance or install door opener.	Carl Johns		101312	FY 2026	
Courtroom 2B Jury Left- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 50" high, 37" depth sink space. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	102432 102434	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 2B Jury Right- Restroom	Inadequate turning space, door opens into clear space, mirror mounted 45" high, 37.5" depth sink space. No grab bars.	Requires remodeling to create space. Move mirror to 40". Install grab bars	Carl Johns	Clearance requirements- Sink: 30"W x 48"D Floor space: 60" diameter circle.	102441 102443	FY 2026	
2 <sup>nd</sup> Floor South Glass Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		103227	Complete	
2 <sup>nd</sup> Floor South Stairs Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		103455	Complete	
2 <sup>nd</sup> Floor North East Judge Office Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		103708	Complete	
2 <sup>nd</sup> Floor North East Judge Office Hearing Room Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		103700	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor South East Judge Office Door	Requires more than 5lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		104250	Complete	
2 <sup>nd</sup> Floor South East Judge Office Conference Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		104253	Nov 2025	
3 <sup>rd</sup> Floor North East Judge Office Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		104941	Complete	
3 <sup>rd</sup> Floor North East Judge Conference Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns			Nov 2025	
2 <sup>nd</sup> Floor South West Judge Office Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		105843	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor North Glass Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		110125	Complete	
2 <sup>nd</sup> Floor North Stairs Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		110132	Complete	
2 <sup>nd</sup> Floor North West Judge Office Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		110941	Complete	
2 <sup>nd</sup> Floor North West Judge Hearing Room	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		110946	Nov 2025	
1 <sup>st</sup> Floor North Office Main Door	Requires more than 5 lbs to open.	Adjust or replace door openers.	Carl Johns		112042 112219	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor South Office Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns		112931	Nov 2025	
1 <sup>st</sup> Floor South Stairs Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		113001	Complete	
Marriage License Office Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		113325	Complete	
1 <sup>st</sup> Floor South Office Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		113317	Complete	
1 <sup>st</sup> Floor South Office Double Doors	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		114100	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor South Office Main Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		114420	Complete	
Basement Right- Restroom Door	Requires more than 5 lbs to open. Swings inward.	Adjust or replace door closer. Change door to swing out.	Carl Johns			Nov 2025	
Basement Right- Restroom	Coat hooks mounted 56" high. Water closet centerline 20.5" from side wall.	Move coat hooks to 48". Move water closet to be 16-18" from side wall.	Carl Johns		0991 0992	Nov 2025	
Basement Left- Restroom	Coat hooks and paper towel dispenser mounted at 52". 42"D sink free space.	Move coat hooks and paper towels to 48". Create 48" free space in front of sink.	Carl Johns	Clearance requirements- Sink: 30"W x 48"D	0993 0994	Nov 2025	
Basement Left- Restroom Door	Requires more than 5 lbs to open. Swings inward.	Adjust or replace door closer. Change door to swing outward.	Carl Johns			Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
South Stairway	Handrails too large to grip.	Replace handrails.	Carl Johns	Handrails should have a cross section of 1.25-2".	980 981	Nov 2025	
North Stairway	Handrails too large to grip.	Replace handrails.	Carl Johns	Handrails should have a cross section of 1.25-2".	980 981	Nov 2025	
East Stairway	Handrails too large to grip.	Replace handrails.	Carl Johns	Handrails should have a cross section of 1.25-2".	980 981	Nov 2025	
Parking	No accessible parking.	Create accessible parking space.	Carl Johns	One space on south- west marked for ASO court security could be repainted & parking sign installed to make accessible.	976 977	Nov 2025	
Room 303 Sign	Mounted at 62″ high.	Lower to 60".	Carl Johns		983	Nov 2025	

Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Mounted at 66″ high.	Lower to 60".	Carl Johns		984	Nov 2025	
Mounted at 62″ high.	Lower to 60".	Carl Johns			Nov 2025	
Mounted at 63″ high.	Lower to 60".	Carl Johns			Nov 2025	
Mounted at 65″ high.	Lower to 60".	Carl Johns			Nov 2025	
Mounted at 63″ high.	Lower to 60".	Carl Johns			Nov 2025	
	Mounted at 66" high. Mounted at 62" high. Mounted at 63" high. Mounted at 65" high.	Mounted at 66" high.Lower to 60".Mounted at 62" high.Lower to 60".Mounted at 62" high.Lower to 60".Mounted at 63" high.Lower to 60".Mounted at 65" high.Lower to 60".Mounted at 65" high.Lower to 60".	Access IssueSolutionResponsibleMounted at 66" high.Lower to 60".Carl JohnsMounted at 62" high.Lower to 60".Carl JohnsMounted at 63" high.Lower to 60".Carl JohnsMounted at 63" high.Lower to 60".Carl JohnsMounted at 65" high.Lower to 60".Carl JohnsMounted at 65" high.Lower to 60".Carl Johns	Access Issue   Solution   Responsible   Comments     Mounted at 66"   Lower to 60".   Carl Johns   Image: Comments     Mounted at 62"   Lower to 60".   Carl Johns   Image: Comments     Mounted at 62"   Lower to 60".   Carl Johns   Image: Comments     Mounted at 63"   Lower to 60".   Carl Johns   Image: Comments     Mounted at 63"   Lower to 60".   Carl Johns   Image: Comments     Mounted at 65"   Lower to 60".   Carl Johns   Image: Comments     Mounted at 65"   Lower to 60".   Carl Johns   Image: Comments     Mounted at 63"   Lower to 60".   Carl Johns   Image: Comments     Mounted at 63"   Lower to 60".   Carl Johns   Image: Comments	Access Issue   Solution   Responsible   Comments   Photo     Mounted at 66"   Lower to 60".   Carl Johns   984     Mounted at 62"   Lower to 60".   Carl Johns   984     Mounted at 62"   Lower to 60".   Carl Johns   984     Mounted at 63"   Lower to 60".   Carl Johns   984     Mounted at 63"   Lower to 60".   Carl Johns   984     Mounted at 63"   Lower to 60".   Carl Johns   984     Mounted at 65"   Lower to 60".   Carl Johns   984     Mounted at 65"   Lower to 60".   Carl Johns   984	Access IssueSolutionPerson ResponsibleCommentsPhotoCompletion DateMounted at 66" high.Lower to 60".Carl Johns984Nov 2025Mounted at 62" high.Lower to 60".Carl JohnsImage: Solution of the solu

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Room 409 Sign	Mounted at 65″ high.	Lower to 60".	Carl Johns			Nov 2025	
3 <sup>rd</sup> Floor North East Judge Office Sign	Mounted at 65″ high.	Lower to 60".	Carl Johns			Nov 2025	
3 <sup>rd</sup> Floor North West Judge Office Sign	Mounted at 65″ high.	Lower to 60".	Carl Johns			Nov 2025	
3 <sup>rd</sup> Floor Men's Restroom Sign	Mounted at 65″ high.	Lower to 60".	Carl Johns			Nov 2025	
3 <sup>rd</sup> Floor South East Judge Office Sign	Mounted at 65″ high.	Lower to 60".	Carl Johns			Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
3 <sup>rd</sup> Floor South West Judge Office Sign	Mounted at 65″ high.	Lower to 60".	Carl Johns			Nov 2025	
2 <sup>nd</sup> Floor Men's Restroom Sign	Mounted at 65" high.	Lower to 60".	Carl Johns			Nov 2025	
1 <sup>st</sup> Floor Men's Restroom Sign	Mounted at 65″ high.	Lower to 60".	Carl Johns			Nov 2025	
2 <sup>nd</sup> Floor South West Judge Hearing Room Door	Requires more than 5 lbs to open. Closes faster than 5 seconds. Hardware requires gripping and twisting.	Adjust or replace door closer. Replace hardware with accessible handle.	Carl Johns		105846	Nov 2025	

## **ADA Transition Plan**

Facility Wilson Building	Date <u>12/19/2018</u>
Contact Person Carl Johns	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone <u>352-384-3190</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Court Services (C.S.) North-East Exit-Only Door	Closes in less than 5 seconds, requires over 5 lbs force to open, 17" maneuvering clearance on latch side, bottom 10" not smooth.	Replace door or add push button door opener on inside.	Carl Johns	Door is exit only, with pull side on outside. May not require any work.	100353	Nov 2025
1 <sup>st</sup> Floor Interior Ramp to Offices	Doesn't have handrail on left-side	Install left-side handrail	Carl Johns	Moving to new building 2024	101405 101431	Nov 2025
1 <sup>st</sup> Floor Interior Ramp to North- Rear Exit	Doesn't have handrail on left-side	Install left-side handrail	Carl Johns	Moving to new building 2024	101722	Nov 2025

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Interior Ramp C.S. Door	Requires more than 5 lbs of force to open.	Adjust or replace door closer.	Carl Johns		102410	Complete	
1 <sup>st</sup> Floor C.S. North Men's Restroom	Coat hooks mounted higher than 48".	Move coat hooks to 48".	Carl Johns		102744 102747 102750	Nov 2025	
1 <sup>st</sup> Floor C.S. North Men's Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		102805	Complete	
1 <sup>st</sup> Floor C.S. North Women's Restroom Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		103556	Complete	
1 <sup>st</sup> Floor C.S. North Women's Restroom	Coat hooks mounted higher than 48".	Move coat hangers to 48".	Carl Johns		103910 103914 103918	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor C.S. North Women's Restroom Stalls	No grab bars, stall door not closing, stall less than 56x60".	Remodel Restroom.	Carl Johns	Moving to new building 2024	104210 104218 104227	FY 2027	
1 <sup>st</sup> Floor C.S. South-Rear Door	Closes faster than 5 seconds.	Adjust or replace door closer	Carl Johns	Not public access door. Leads to fenced- in A.C. Units and Elevator Mechanical Room	105004	Complete	
1 <sup>st</sup> Floor C.S. Lobby West Door	Less than 18" maneuvering clearance on latch side. Closes in less than 5 seconds. Requires more than 5lbs force to open.	Adjust or replace door closer. Install push button door opener on inside.	Carl Johns	Moving to new building 2024	105146	Nov 2025	
1 <sup>st</sup> Floor C.S. Door in front of elevator	55" maneuvering clearance on pull side of door. Requires more than 5 lbs of force to open.	Adjust or replace door closer. Move obstructions so there is 60" maneuvering clearance.	Carl Johns	Moving to new building 2024	105558 105946 105956	Nov 2025	
1 <sup>st</sup> Floor C.S. South Women's Restroom Door	42" maneuvering clearance on push- side. Requires more than 5 lbs force to open.	Adjust or replace door closer. Remove opposing wall to give clearance.	Carl Johns	Moving to new building 2024	111017	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor C.S. South Women's South Restroom	Mirrors mounted 44" above ground. Coat Hooks 61". Paper Towel Dispenser 51"	Move mirrors to 40" above ground. Move paper towel dispenser and coat hooks to 48".	Carl Johns	Moving to new building 2024	111417 111423 111436 111445 112328 112333 112342 112430	Nov 2025	
1 <sup>st</sup> Floor C.S. South Men's Restroom Door	Closes in less than 5 seconds. More than 5 lbs to open. 42.5" push-side clearance for maneuvering.	Adjust or replace door closer. Create maneuvering clearance.	Carl Johns		112648	Nov 2025	
1 <sup>st</sup> Floor C.S. South Men's Restroom	Coat hook mounted 64" above ground. Paper towel dispenser 50".	Move coat hooks and paper towel dispensers to 48".	Carl Johns		112944 112948 112956	Nov 2025	
1 <sup>st</sup> Floor C.S. Restroom Hallway Door	6" maneuvering clearance on latch side of door.	Add push button door opener or remove door.	Carl Johns	Moving to new building 2024	113610 113630 113708	Nov 2025	
1 <sup>st</sup> Floor C.S. South-West Hallway Door	7" maneuvering clearance on latch side. 41" maneuvering clearance on pull- side.	Create 18" clearance on latch side and 60" maneuvering clearance on pull- side.	Carl Johns	Moving to new building 2024	113844	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor C.S. Office Door	43" maneuvering clearance on push- side, and 41" on pull-side.	Create 48" clearance on push- side, 60" on pull- side.	Carl Johns	Moving to new building 2024	114428	FY 2027	
1 <sup>st</sup> Floor C.S. Office Door	43" maneuvering clearance on push- side. Handle requires gripping and twisting wrist.	Create 48" clearance on push-side, 60" on pull-side. Replace with accessible handle.	Carl Johns	Moving to new building 2024	114754	FY 2027	
1 <sup>st</sup> Floor C.S. Office Door	42" maneuvering clearance on push- side, 40" on pull- side.	Create 48" clearance on push-side, 60" on pull-side.	Carl Johns	Moving to new building 2024	94735	FY 2027	
1 <sup>st</sup> Floor C.S. Office Door	14" side maneuvering clearance on latch side.	Create 18" clearance.	Carl Johns	Moving to new building 2024	95009	FY 2027	
1 <sup>st</sup> Floor C.S. Office Door	7" maneuvering clearance on latch side. 43" clearance on push-side.	Create 18" on clearance on side. Create 48" clearance on push- side.	Carl Johns	Moving to new building 2024	95115	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor C.S. Office Door	33" pull-side clearance.	Create 60" clearance.	Carl Johns	Should be able to create clearance by moving furniture.	95530	FY 2027	
South Exit-Only Door.	More than 5lbs to open. Closes in less than 5 seconds. Bottom 10" not smooth, not 18" maneuvering clearance on latch side.	Adjust or replace door closer. Replace door. Make clearance.	Carl Johns	Exit only, push side on inside. 18" clearance only required for pull- side of door.	95629	Nov 2025	
1 <sup>st</sup> Floor C.S. Office Door	36" clearance on pull-side.	Create 60" clearance.	Carl Johns	Moving to new building 2024	100110	FY 2027	
1 <sup>st</sup> Floor C.S. Office Door	49" pull-side clearance, 6" maneuvering clearance on latch- side	Create 60" pull-side clearance, 18" maneuvering clearance.	Carl Johns	May be able to move furniture to create space.	100927	FY 2027	
1 <sup>st</sup> Floor C.S. Office Door	36" on pull-side	Create 60" pull-side clearance	Carl Johns	May be able to move furniture to create space.	101512	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor C.S. Office Door	47" clearance on push-side, 37" on pull-side	Create 60" pull-side clearance, 48" push-side clearance.	Carl Johns	May be able to move furniture to create space.	101657	FY 2027	
1 <sup>st</sup> Floor C.S. South East Hallway door	9" maneuvering clearance on latch- side. Hardware mounted 54" above ground.	Create 18" clearance, move hardware to 48".	Carl Johns	Moving to new building 2024	101847	FY 2027	
1 <sup>st</sup> Floor C.S. Lobby South Door	6" maneuvering clearance on latch- side, closes in less than 5 seconds.	Create clearance. Adjust or replace door closer.	Carl Johns	Security Door requires keycard or clerk to open.	102214	Nov 2025	
1 <sup>st</sup> Floor C.S. Office Door	40" pull-side clearance.	Create 60" clearance.	Carl Johns	May be able to move furniture to create space.	102219	FY 2027	
1 <sup>st</sup> Floor C.S. Office Door	30" pull-side clearance.	Create 60" clearance.	Carl Johns	May be able to move furniture to create clearance.	102753	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor C.S. Office Door	43" push-side clearance. 4" maneuvering clearance on latch- side.	Make 48" clearance on push-side, 18" clearance on latch- side.	Carl Johns	May be able to move furniture to create clearance.	102852	FY 2027	
2 <sup>nd</sup> Floor C.S. Men's Restroom Door	41" clearance push- side, 11" maneuvering clearance on latch- side. Requires more than 5 lbs open.	Create 48" clearance on push-side, 18" on latch-side. Adjust or replace door closer.	Carl Johns	Moving to new building 2024	103740	FY 2027	
2 <sup>nd</sup> Floor C.S. Men's Restroom	Mirrors mounted at 47", coat hooks at 70". 36" clearance around water closet. No grab bars. Stall door not self-closing.	Remodel restroom to bring into compliance.	Carl Johns	Moving to new building 2024	103459 103459 104711 104717 104722	FY 2027	
2 <sup>nd</sup> Floor C.S. Women's Restroom Door	25" pull-side clearance. Requires more than 5 lbs to open.	Adjust or replace door closer. Create 60" pull-side clearance	Carl Johns		104842	FY 2027	
2 <sup>nd</sup> Floor C.S. Women's restroom	Mirrors mounted at 47", coat hooks at 71". No grab bars, 36" clearance around water closets.	Remodel restroom to bring into compliance.	Carl Johns	Moving to new building 2024	104756 104903 104911 105503 105537 105852	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor C.S. Water Fountain	Water flow 3.5″ high.	Adjust so water flows up 4".	Carl Johns	Moving to new building 2024	110127	Complete	
C.S. Lobby Stairs	Right-side handrail not in compliance.	Replace with rail than can be gripped.	Carl Johns	Moving to new building 2024	110441	FY 2027	
C.S. Lobby Entrance Door.	Closes in less than 5 seconds, requires more than 5 lbs to open. Bottom 10" not smooth.	Adjust or replace door closer. Replace door.	Carl Johns		110434	Complete	
1 <sup>st</sup> Floor I.T. North Entrance	Closes in less than 5 seconds, requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns	Not Public access, requires keycard access, behind key- lock gate.	134	Complete	
1 <sup>st</sup> Floor I.T. Right-side Restroom	Coat hooks mounted at 66".	Move coat hooks to 48".	Carl Johns		135	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor I.T. Left- side Restroom	Coat hooks mounted at 66".	Move coat hooks to 48".	Carl Johns		136	Nov 2025	
I.T. North Stairs	Hand rails not in compliance.	Replace hand rails so they are 34-38" tall.	Carl Johns	Moving to new building 2024	137	FY 2027	
2 <sup>nd</sup> Floor I.T. Right-Side Restroom	Side grab-bar doesn't extend 54" from rear wall.	Move or replace side-grab bar so it extends 54" from, and is not more than 12" from rear wall	Carl Johns	Moving to new building 2024	139 140	FY 2027	
2 <sup>nd</sup> Floor I.T. Right-Side Restroom	Paper towel dispenser mounted at 50".	Move to 48".	Carl Johns		141 142 143	May 2025	
2 <sup>nd</sup> Floor I.T. Break Room Door	Handle requires gripping and twisting of wrist.	Replace hardware with accessible handle.	Carl Johns		145	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor I.T. Lobby Phone	Phone mounted on wall 50" tall.	Move to 48".	Carl Johns	Phone is for public use.	151 153	May 2025	
1 <sup>st</sup> Floor I.T. East Lobby Door	Closes in less than 5 seconds, requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		152 135342	Complete	
1 <sup>st</sup> Floor Visitor Center Front Door	Closes in less than 5 seconds, requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		141752	Complete	
Accessible parking	Needs curb ramp and signage.	Install curb ramp and required signage.	Carl Johns	Moving to new building 2024	128	FY 2027	

## **ADA Transition Plan**

Facility Adr	min Building	Date <u>12/20/2018</u>
Contact Person	Carl Johns	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone <u>352-384-3190</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion F Date	Priority
North East Double Door Entrance	Requires more than 5 lbs to open, bottom 10" not smooth.	Adjust or replace door closer. Replace door.	Carl Johns	Has push-button door opener. Opens to outdoor stairs. May not require modification.	95251	Complete	
1 <sup>st</sup> Floor North East Inner Double Doors	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closers.	Carl Johns	These doors are normally kept open during business hours.	95748 95749	Complete	
Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		100028	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
1 <sup>st</sup> Floor Stairs Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		100536	Complete	
Stairs	Handrails too large.	Replace both sides of handrails.	Carl Johns		100745	FY 2025	
Tax Collector Glass Lobby Doors	Requires more than 5 lbs to open. Closes faster than 5 seconds. Lower 10" not smooth.	Adjust or replace door closer. Replace door.	Carl Johns	Has push-button door opener. May not require modification.	101342	Complete	
Men's Restroom Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		101653 101720	Complete	
Men's Restroom	Paper Towels mounted 52" high.	Move paper towels to 48".	Carl Johns		102049 102105 102122 102105 102145 102714	Jan 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom	Coat hook mounted 53" high. Rear grab bar inadequate, no side grab bar. Stall door not self- closing.	Move coat hooks to 48". Install new grab bars. Install stall door closer.	Carl Johns		135814 135817 135820 135826	Jan 2025	
Women's Restroom	Coat hooks mounted at 53" high. Stall door not self- closing.	Move coat hooks to 48". Install stall door closer.	Carl Johns		104609 104613 104625	Jan 2025	
ACSO "Civil Bureau" Entrance Door	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		105738	Complete	
HR Office Entrance Door	Requires more than 5 lbs to open. Closes faster than 5 seconds. Lower 10" not smooth.	Adjust or replace door closer. Replace door.	Carl Johns		110229	Complete	
Door	Requires more than 5 lbs to open. Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		111307	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Interior Stairs	Handrails not compliant.	Replace handrails.	Carl Johns		111643	June 2025	
Door	Requires more than 5 lbs to open. Closes faster than 5 seconds. 11" latch- side clearance.	Adjust or replace door closer. Make 18" clearance on latch side.	Carl Johns		110901	Complete	
North West Double Entrance Door	Requires more than 5 lbs to open. Lower 10" not smooth.	Adjust or replace door closer. Replace doors.	Carl Johns		110841	Complete	
Tax Collector East Double Entrance Door	Requires more than 5 lbs to open. Lower 10″ not smooth.	Adjust or replace door closers. Replace doors.	Carl Johns		95507	Complete	
Family Restroom	Mirror mounted at 42" high. Coat hooks at 60. Paper towels at 54".	Move Mirror to 40", coat hooks to 48", paper towels to 48".	Carl Johns		100227 100229 100234	June 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Glass Double Doors	Lower 10" of door not smooth.	Replace doors.	Carl Johns		101850	July 2025	
Water Fountain	Height of water flow 3.5"	Adjust water flow to 4" high.	Carl Johns		102230	Complete	
Men's Restroom Door	Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		102556	Complete	
Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		102613	Complete	
Men's Restroom	Mirror mounted at 46″ high.	Move mirror to 40".	Carl Johns		102643 102646 102649	May 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Restroom	Coat hooks 66" high. Stall door not self- closing.	Move coat hooks to 48". Install stall door closer.	Carl Johns		102659 102702	May 2025	
Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		105035	Complete	
Restroom	Mirror mounted at 42" high. Coat hooks at 64". Paper towels at 52".	Move mirror to 40". Move coat hooks and paper towels to 48".	Carl Johns		105409 105419 105434	May 2025	
Stairs Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		105636	Complete	
Manager's Office Entrance Double Doors.	Requires more than 5 lbs to open. Bottom 10" not smooth.	Adjust or replace door closer. Replace doors.	Carl Johns		110039	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Door	6.5" latch-side clearance.	Modify so there is 18" maneuvering clearance on the latch-side.	Carl Johns		110714	May 2025	
Double Glass Doors	Requires more than 5 lbs to open. Lower 10" not smooth.	Adjust or replace door closer. Replace doors.	Carl Johns		111047	May 2025	
Stairs Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		111207	Complete	
Stairs Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		111830	Complete	
Finance & Accounting Double Glass Doors	Requires more than 5 lbs to open, closes faster than 5 seconds. Lower 10" not smooth.	Adjust or replace door closer. Replace doors.	Carl Johns		112009	May 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Outside South Stairs	Handrails are not compliant.	Replace handrails with 1.25-1.5" diameter rail.	Carl Johns		114247	FY 2026	
South Exit	Requires more than 5 lbs to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		114449	Complete	
Inside Stairway	Handrails are not compliant.	Replace handrails with 1.25-1.5" diameter rail.	Carl Johns		114454 114502	FY 2026	
Restroom	Mirror mounted 47" high, coat hooks at 71", paper towels at 54". Trashcan blocks sink clearance.	Move mirror to 40". Move paper towels & coat hooks to 48". Move trashcan to clear sink floor space.	Carl Johns		383 384 385 386 387	May 2025	
Restroom	Mirror mounted 47" high, coat hooks at 71", paper towels at 54". Trashcan blocks sink clearance.	Move mirror to 40". Move paper towels & coat hooks to 48". Move trashcan to clear sink floor space.	Carl Johns		391 392 393 394	May 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Unisex Restroom	Mirror mounted at 47".	Move mirror to 40".	Carl Johns	Room 153	397 398 399 400	May 2025	
Grace Knight Conference Double Doors	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		403	Complete	
Accessible parking.	Accessible parking brick surface is uneven.	Concrete paving or re-surface parking spot.	Carl Johns		145748 145750 145807 145817	FY 2026	
Service Counter	Counter is 42.5" tall.	Replace with counter that doesn't exceed 36" or has a 36" tall section 36" wide.	Carl Johns		113215	FY 2026	
Room Signs	Many room signs do not have braille.	Replace with sign that includes braille.	Carl Johns	These are just a few example pictures. There are many more doors that do not have braille signage.	100315 102556 102600 105636 110039	May 2025	

## **ADA Transition Plan**

Facility Main Street Legal	Date <u>5/30/2019</u>
Contact Person <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone <u>352-384-3190</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priorit Date
Court Services Main Entrance	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		1706	Complete
Conference Room Door	Furniture blocking clear floor space.	Move furniture.	Carl Johns		1707	Complete
Men's Staff Restroom Door	28" wide, bottom 10" of door not smooth.	Requires replacement.	Carl Johns	Moving to new building 2023	1708 1709	Jan 2026

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Restroom	Mirror mounted at 43" high. Urinal & Stall not accessible.	Move mirror to 40". Requires remodeling to make accessible.	Carl Johns	Moving to new building 2023	1710 1711 1712	FY 2027	
Restroom	Stalls are not accessible.	Requires remodeling.	Carl Johns	Moving to new building 2023	1713	FY 2027	
Women's Staff Restroom Door	28" wide, bottom 10" of door not smooth.	Requires replacement.	Carl Johns	Moving to new building 2023	1716	FY 2027	
Restroom Sink	Pipes under sink are not insulated.	Install insulation.	Carl Johns		1717	March 2025	
Restroom Stall	Door swings in, not self-closing, no grab bars, coat hook at 67", water closet 24" from side wall.	Requires remodel to make compliant.	Carl Johns	Moving to new building 2023	1718	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Restroom Stall	Door swings in, not self-closing, no grab bars, coat hook at 67", water closet 24" from side wall.	Requires remodels to make compliant.	Carl Johns	Moving to new building 2023	1719	FY 2027	
Unisex Accessible Restroom Door	Requires more than 5 lbs to open.	Adjust or replace door closer.	Carl Johns		1722	Complete	
Unisex Accessible Restroom	Mirror mounted 48" high. Paper towel dispenser mounted 49".	Move mirror to 40" and paper towels to 48".	Carl Johns	Moving to new building 2023	1723	March 2025	
Interview Room Door	Needs new door closer.	Install door closer.	Carl Johns		1727	March 2025	
Restroom Door	Needs door closer.	Install door closer.	Carl Johns			March 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Staff Restroom Door	Threshold in front of door taller than ½".	Bevel threshold.	Carl Johns		1735	May 2025	
Staff Single Restroom	Flush controls on closed side.	Replace flush control with right-side model.	Carl Johns	Moving to new building 2023	1736	May 2025 March 2025	
Office Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns	Moving to new building 2023	1737	May 2025	
Hallway Door	Hardware requires gripping and twisting.	Replace hardware with accessible handle.	Carl Johns	Moving to new building 2023	1738	May 2025	
Visit Gainesville Front Door	5" step down from doorstep to sidewalk.	Requires ramp.	Carl Johns	Moving to new building 2023	1739 1740 1741 1742	FY 2027	

Facility	34 <sup>th</sup> Tag Agency / New ACFR Training Building	<b>Date</b> <u>5/2</u>	7/2020
Contact F	Person <u>Carl Johns</u>	Department	ACFM
Email	fjohns@alachuacounty.us	Phone	352-384-3190

Target Person Solution **Photo Completion Priority** Access Issue Comments Area Responsible Date Accessible Only 2 spaces in 53 Reconfigure to add 1 Carl Johns Moving to New Complete 7.16 more accessible Parking spaces car lot. Building 2022 space with access lane. 39" tall and 35" Replace with Carl Johns Moving to New 7.13 Service Counter Complete accessible counter Building 2022 wide. 7.14 36" tall, 36" wide. Break Room Light Light Switch located Relocate fridge. Carl Johns Moving to New 7.08 Complete Switch behind fridge. Building 2022

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Back Accessible Restroom Sign	Not mounted on latch side.		Carl Johns	Moving to New Building 2022	7.07	Complete	
Back Accessible Restroom Door	Doesn't have 18" maneuvering space on the latch side of door.		Carl Johns	Moving to New Building 2022	7.07	Complete	
Back Accessible Restroom Rear Grab-Bar	Touching water closet.	Raise bar 1.5″	Carl Johns	Moving to New Building 2022	7.05	Complete	
Back Accessible Restroom Toilet Paper Dispenser	Mounted 12" away from water closet.	Move to be 7-9 forward of water closet.	Carl Johns	Moving to New Building 2022	7.06	Complete	
Front Accessible Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns	Moving to New Building 2022	7.09	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Front Accessible Restroom Coat Hooks	Mounted higher than 48"	Lower coat hooks to 48".	Carl Johns	Moving to New Building 2022	7.09	Complete	
Front Accessible Restroom Sink	Surface of sink is 35" above ground.	Lower to 34".	Carl Johns	Moving to New Building 2022	7.12	Complete	
Front Accessible Restroom Toilet Paper Dispenser	Mounted 12" away from water closet.	Move to be 7-9". Move down so there is 1.5" clearance below grab bar. (See Below)	Carl Johns	Moving to New Building 2022	7.11	Complete	
Front Accessible Restroom Side Grab-Bar	Has less than 1.5″ clearance underneath.	Move Toilet Paper Dispenser Down. (See above)	Carl Johns	Moving to New Building 2022	7.11	Complete	
Front Accessible Restroom Rear Grab-Bar	Less than 12" clearance above.	Relocated paper towel dispenser.	Carl Johns	Moving to New Building 2022	7.10	Complete	

Facility	Criminal Justice Center	Date <u>4/29/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department <u>ACFM</u>

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion I Date	Priority
Judge's Bathroom: Rear Grab-bar	Rear grab-bar is only 32", should be at least 36" and have at least 12" of clearance above the grab-bars.	Replace grab-bar with one that is at least 36" Move soap dispenser so that there is 12" of clearance above the grab-bars.	Carl Johns	Sink need to be moved to allow for 36" bar.	8.21	June 2025	
Restrooms Paper Towel Dispensers	Mounted above 48", should be no more than 48".	Move so they are no more than 48" to the floor.	Carl Johns		8.04 8.22 8.23 8.50 8.61	June 2025	
Judge Area in Courtroom	No ramp leading up to the judge area, only stairs.	Replace the stairs with a ramp or add a ramp that allows access to the judge's area.	Carl Johns		8.34 8.48 8.52 8.58 8.59	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Courtroom 2E: Wheelchair Spaces	Only has 1 wheelchair space, but has a maximum occupancy of 31 people, should have 2 spaces when more than 25 people.	Add another section for wheelchairs or make the section wider so that it can allow for two wheelchairs.	Carl Johns		8.35 8.33 8.54	June 2025	
All Accessible Restrooms: Stall Doors	Accessible stall door does not have handles on both sides and is not self-closing.	Add door pulls on both sides of stall doors and adjust so they are self- closing.	Carl Johns		8.41 8.42 8.43 8.44 8.45 8.46 8.49 8.51 8.56 8.60	June 2025	
3 <sup>rd</sup> Floor Women's Restroom Sign	Some of sign does not contrast.	Replace or modify sign so it contrasts.	Carl Johns		8.55	June 2025	

Facility _	Hazardous Waste	Date <u>5/7/2020</u>
Contact Per	rson <u>Carl Johns</u>	Department ACFM

Email fjohns@alachuacounty.us Phone 352-384-3190

FY 2026

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Door	Less than 18" maneuvering clearance on latch side of door.	Relocate fridge that is blocking maneuvering space.	Carl Johns		9.01	Complete	
Accessible Restroom Water Closet	Mounted 19" from side wall.	Move to be 16-18" from centerline of water closet to side wall.	Carl Johns		9.03	FY 2026	
Accessible Restroom Toilet Paper Dispenser	Mounted 12" in front of water closet.	Move to 7-9" forward of water closet.	Carl Johns		9.03		

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Main Entrance Door	Closes in less than 5 seconds.	Adjust or replace door closer so that it takes at least 5 seconds to close.	Carl Johns		9.12	Complete	

Facility	Health Department State	Date <u>5/1/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion I Date	Priority
Accessible Restrooms: Rear Grab-bars	Water closets rear grab-bars are not at least 36" or extend 24" on the open side of the water closet.	Replace grab-bars with ones that are at least 36" long and extend 24" on the open side and 12" on the closed side.	Carl Johns		10.03 10.06 10.09 10.10 10.15	June 2025	
Accessible Restrooms: Paper Towel Dispensers	Paper towel dispensers are mounted higher than 48" above the ground.	Move paper towel dispensers so that they are no more than 48" from the bottom to the floor.	Carl Johns		10.04 10.07 10.11 10.16	June 2025	
Accessible Restrooms: Coat Hooks	Coat hooks are 63" above the ground, should be no more than 48".	Move coat hooks so that they are no more than 48" to the floor.	Carl Johns		10.05 10.08 10.12	June 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Locker Room Benches	Benches are only 14.5" deep, should be 20-24" deep.	Replace bench with ones that are at least 20" and no more than 24" deep.	Carl Johns		10.27	FY 2027	
Service Counter	Service counters have less than 27" clearance underneath, should have at least 27" of clearance for knee space.	Adjust service counters so that there is at least 27" of knee space underneath.	Carl Johns		10.29 10.30	FY 2027	

Facility Heal	th Department County	<b>Date</b> <u>5/</u>	/5/2020_
Contact Person	Carl Johns	Department	L ACFM

Email <u>fjohns@alachuacounty.us</u>

**Phone** 352-384-3190

Target Person Solution **Photo Completion Priority Access Issue** Comments Area Responsible Date All Accessible Paper towel Move paper towel May 2025 Carl Johns 11.01 Restrooms: dispensers are dispensers so that 11.02 more than 48" they are no more 11.04 Paper Towel above the ground. than 48" from the 11.08 Dispensers bottom to the floor. 11.10 11.11 11.13 11.15 11.19 Accessible Replace grab-bars Water closet rear Carl Johns 11.03 Restrooms: Rear grab-bars are less with ones that are 11.07 than 36" long and 36" long and Grab-bars 11.09 do not extend 24" extend 12" on the June 2025 11.12 open side of the 11.14 on the open side of the water closet. water closet. Move 11.18 Must also have 12" any objects so that 11.23 of clearance above there is 12" of 11.24 grab-bars. clearance above 11.25 11.29 grab-bars. 11.33

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restrooms: Flush Control	Flush control is located on the closed side of the water closet instead of the open side.	Move flush control so that it is located on the open side of the water closet.	Carl Johns		11.34	June 2025	
All Accessible Restrooms: Coat Hooks	Coat hooks are 73" from the ground should be no more than 48".	Move coat hooks so that they are no more than 48" from the ground.	Carl Johns		11.37	May 2025	
All Accessible Restrooms: Door Closer	Door closer is faster than 5 seconds, should take at least 5 seconds to close.	Adjust door closer so that it takes 5 seconds minimum to close.	Carl Johns		11.56	Complete	

Facility JT W	/alls	Date <u>4/30/2020</u>
Contact Person	Carl Johns	Department _ ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Accessible Restroom: Stall Door	No handles on the inside of the accessible stall door. Should have door pulls on both sides of stall doors.	Add handles on inside of accessible stall door.	Carl Johns		12.08	July 2025
Van Accessible Parking Sign	No van accessible parking sign at the van accessible parking spaces.	Add a sign that says van accessible at the van accessible parking spaces.	Carl Johns		12.11	July 2025
Accessible Restrooms: Side Grab-bars	Side grab-bars are only 36" long, should be at least 42" long and have 12" clearance above.	Replace side grab- bars with grab-bars that are 42" and remove any objects that do not allow for 12" clearance above.	Carl Johns		12.20	July 2025

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Elevators	Elevator is only 43" deep, should be a minimum of 54" deep.	Make accommodations so that at least one elevator is 54" deep and accessible.	Carl Johns	Depending on when the building was built, this may or may not be required.		FY 2028	

Facility	Metamorphosis	Date <u>5/26/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department <u>ACFM</u>

Email <u>fjohns@alachuacounty.us</u>

**Phone** 352-384-3190

Target Person Solution **Photo Completion Priority Access Issue** Comments Area Responsible Date Non-accessible No accessible Remodel some Carl Johns May require major 13.02 Restrooms restrooms. restrooms to be remodeling. 13.03 13.04 ADA compliant. FY 2028 Front Restroom Does not have raised Install new ADA Carl Johns 13.01 accessible sign. Sign characters and braille. Not mounted on wall, July 2025 latch side. Shower Door Replace with ADA Carl Johns **Requires** gripping 13.05 Handle compliant and twisting. hardware. July 2025

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Parking Space	Space is not "van accessible."	Widen space or access aisle.	Carl Johns		13.06		
						July 2025	

Facility _/	Admin Transfer Station	Date <u>5/7/2020</u>
Contact Pers	on <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Van Accessible Parking	Not marked as "Van Accessible."	Install "Van Accessible" sign.	Carl Johns		14.01 14.08 14.10	July 2025
All Light Switches	Mounted 49" above the floor.	Move to 48".	Carl Johns		14.19	July 2025
Women's Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		14.07	Complete

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Accessible Stall Coat Hook	Mounted 64" above ground.	Move to 48".	Carl Johns		14.13	July 2025	
Women's Restroom Accessible Mirror	Mounted 44" above ground.	Move to 40".	Carl Johns		14.03	July 2025	
Women's Restroom Accessible Stall Door	Doesn't have handles on both sides. Isn't self- closing.	Install handles on both sides of door. Install door closer.	Carl Johns		14.13	July 2025	
Women's Restroom Side Grab Bar	Doesn't extend 54" from rear wall.	Move to be 12" away from rear wall.	Carl Johns	Bar is long enough.	14.02	July 2025	
Women's Restroom Rear Grab Bar	Doesn't have 12" clearance above.	Relocate seat cover dispenser.	Carl Johns		14.02	July 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		14.09	Complete	
Men's Restroom Accessible Stall Coat Hook	Mounted 60″ above ground.	Move to 48".	Carl Johns		14.06	July 2025	
Men's Restroom Accessible Stall Door	Doesn't have handles on both sides. Isn't self- closing.	Install handles on both sides. Install door closer.	Carl Johns		14.06	July 2025	
Men's Accessible Restroom Mirror	Mounted 44" above ground.	Move to 40".	Carl Johns		14.05	July 2025	
Men's Restroom Rear Grab Bar	Doesn't have 12" clearance above. Only extends 21" from centerline of water closet to open side.	Relocate seat cover dispenser. Move bar 3" to open side.	Carl Johns	Bar long enough.	14.04	July 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Side Grab Bar	Doesn't extend 54" from rear wall.	Move to be 12" away from rear wall.	Carl Johns	Bar long enough.	14.04	July 2025	
Water Fountains	Leading edge higher than 27". Protrudes 18" into path to restrooms.		Carl Johns		14.18	July 2025	

Facility	Records Retention	Date <u>5/28/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion I Date	Priority
Service Counter	Counter doesn't have accessible section.	Replace or add accessible counter: 36" tall, 36"wide.	Carl Johns		15.20 15.21	FY 2026	
Unisex Restroom Water Closet	Flush control located on closed side.	Replace water closet with flusher on open side.	Carl Johns		15.07	Oct 2025	
Unisex Restroom Mirror	Mounted 43" above ground.	Move to 40".	Carl Johns		15.12	Oct 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Unisex Restroom Soap Dispenser	Mounted 58" above floor.	Move to 48".	Carl Johns	May need to move down to 44", may be considered over sink.	15.04 15.13	Oct 2025	
Men's Restroom Water Closet	Mounted 19" from side wall.	Move so center line of water closet is 16-18" from side wall.	Carl Johns		15.10	FY 2026	
Men's Restroom Mirror	Mounted 43" above ground.	Move to 40".	Carl Johns		15.24	Oct 2025	
Men's Restroom Soap Dispenser	Mounted 58″ above ground.	Move to 48".	Carl Johns	May need to move down to 44", may be considered over sink.	15.26	Oct 2025	
Women's Restroom Water Closet	Mounted 19" from side wall.	Move so center line of water closet is 16-18" from side wall.	Carl Johns		15.14	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Paper Towel Dispenser	Mounted 52" above ground.	Move to 48".	Carl Johns		15.25	May 2025	
Women's Restroom Toilet Paper Dispenser	Mounted 12" forward of water closet.	Move to 7-9" forward of water closet.	Carl Johns		15.15	May 2025	
Women's Restroom Mirror	Mounted 43" above ground.	Move to 40".	Carl Johns		15.11	May 2025	
Women's Restroom Soap Dispenser	Mounted 58″ above ground.	Move to 48".	Carl Johns	May need to move down to 44", may be considered over sink.	15.18	May 2025	
Women's Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		15.19	Complete	
Men and Women's Coat Hooks	Coat hooks are mounted at 72" above the floor. Should be no more than 48".	Move coat hooks down to 48" max.	Carl Johns		15.23	May 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Fire Alarms	Fire alarms are audio only.	Install fire alarms that have flashing lights and audio signals.	Carl Johns		15.22	January 2025	

Facility _	Animal Services	Date <u>5/6/2020</u>
Contact Per	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone 3

352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Accessible Parking sign	Accessible parking sign is not at least 60" above the ground.	Move the accessible parking sign so that it is at least 60" from the bottom of the sign to the ground.	Carl Johns		16.04	June 2025
Locker Room Benches	Benches are only 40" long and 17" deep, should be at least 42" long and 20-24" deep.	Replace or extend benches so that they are 20-24" deep and 42" long.	Carl Johns		16.16	FY 2027
Main Door Closer	Door closes faster than 5 seconds	Adjust door closer so that it takes at least 5 seconds to close.	Carl Johns	Carl Johns	16.17	Complete

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Exterior Ramp on Side of the Building	Ramp handrails do not extend 12" past the ends of the ramp or have a curb barrier of a 4" diameter sphere.	Add handrails that extend at least 12" beyond the surface of the ramp or has a curb barrier of a 4-inch diameter sphere.	Carl Johns		16.18 16.20	FY 2027	
Interior Rooms: Light Switches	Light switches are higher than 48" above the ground.	Move light switches so that they are no more than 48" above the ground.	Carl Johns		16.19	FY 2026	
Accessible Bathroom Mirrors	Mirror is more than 40" from the bottom to the floor.	Move mirror down so that it is no more than 40" from the bottom to the floor.	Carl Johns		16.21	June 2025	
Accessible Bathroom Door Closer	Door closes faster than 5 seconds.	Adjust door closer so that it takes at least 5 seconds for the door to close.	Carl Johns	Carl Johns	16.24	Complete	

Facility       Recycling Transfer Station	<b>Date</b> <u>5/7/2020</u>
Contact Person <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone 3

352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Prior Date
Locker Room Benches	Bench is only 9 ½" deep, should be 20- 24" deep.	Adjust benches or replace so that they are at least 20" deep.	Carl Johns	2 benches.	17.08 17.16	FY 2026
Men and Women's Bathroom Door Closers	Door closes faster than 5 seconds.	Adjust door closer so that it takes at least 5 seconds to close.	Carl Johns		17.12	Complete
Men and Women's Accessible Restroom: Side Grab-bars	Side grab-bars do not extend 54" from the rear wall.	Move the side grab- bars so that they extend at least 54" from the rear wall.	Carl Johns		17.02 17.14	January 2026

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men and Women's Accessible Stall Doors	Accessible stall doors are not self- closing and do not have door handles on both sides.	Adjust stall doors so that they are self- closing and add handles on both sides of the stall doors.	Carl Johns		17.01 17.05 17.15	January 2026	
Men's Accessible Restroom Side Grab-bar	There is not at least 12" of clearance above the side grab-bar.	Move toilet paper dispenser so that there is 12" of clearance above the side grab-bar.	Carl Johns		17.17	May 2025	
Accessible Water Fountain	Fountain is broken.	Repair fountain.	Carl Johns		17.20	Complete	

Facility	Public Defender	Date <u>5/27/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department _ACFM

Email <u>fjohns@alachuacounty.us</u>

**Phone** 352-384-3190

Target Person Solution **Photo Completion Priority** Access Issue Comments Area Responsible Date Install handle on 1<sup>st</sup> Floor Men's Doesn't have Carl Johns 18.02 March 2025 handles on inside. inside. Install door Restroom 18.05 Not self-closing. Accessible Stall closer. Door. 1<sup>st</sup> Floor Doesn't have Install handle on Carl Johns March 2025 18.03 handles on inside. Women's inside. Install door 18.04 Restroom Not self-closing. closer. Accessible Stall Door. 2<sup>nd</sup> Floor Men's Doesn't have Install handle on Carl Johns 18.06 March 2025 handles on inside. inside. Install door Restroom Not self-closing. Accessible Stall closer. Door.

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
2 <sup>nd</sup> Floor Women's Restroom Accessible Stall Door.	Doesn't have handles on inside. Not self-closing.	Install handle on inside. Install door closer.	Carl Johns		18.07	March 2025	

Facility       SWAG Resource Center	Date <u>5/26/2020</u>
Contact Person <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Pric Date	prity
Main Entrance Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		19.12	Complete	
Service Counter	41.5" tall. Doesn't have an accessible section.	Install a section 36" tall and 36" wide.	Carl Johns		19.10	March 2025	
Lobby Mats	Mats in front of main entrance and water fountains are not secured to floor.	Secure or remove mats.	Carl Johns		19.04 19.11	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
All Light Switches	Mounted at 50" above ground.	Move to 48".	Carl Johns		19.13	March 2025	
Left-Side Restroom Mirror	Mounted 45" above ground.	Move down to 40".	Carl Johns	May require removal of metal plate on wall.	19.05	March 2025	
Left-Side Restroom Sink	No clear leg space under sink.	Replace sink.	Carl Johns		19.05	September 2025	
Left-Side Restroom Rear Grab Bar	Only extends 10" from center of water closet to closed side. Mounted 37" above ground.	Move grab bar 2" to closed side, 1" down.	Carl Johns	Bar is long enough. Ensure there is 1.5" clearance underneath when moving.	19.06	March 2025	
Right-Side Restroom Mirror	Mounted 45" above ground.	Move down to 40".	Carl Johns	May require removal of metal plate on wall.	19.07	March 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Right-Side Restroom Sink	No clear leg space under sink.	Replace sink.	Carl Johns		19.07	September 2025	
Right-Side Restroom Rear Grab Bar	Mounted 37" above ground.	Move 1" down.	Carl Johns	Ensure there is 1.5" clearance underneath when moving.	19.09	September 2025	
Right-Side Restroom Water Closet	Mounted 20" away from side wall.	Move so centerline of water closet is 16-18" from side wall.	Carl Johns		19.09	September 2025	

Facility	Work Release	Date <u>5/6/2020</u>
Contact Per	rson <u>Carl Johns</u>	Department <u>ACFM</u>

Email <u>fjohns@alachuacounty.us</u>

Phone 352

352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Prio Date	ority
Main Entrance Door	Door handle mounted 49" above ground.	Lower handle to 48".	Carl Johns		20.04	May 2025	
Room Signs	No raised characters and braille. Not mounted on wall, latch side of door.	Replace signs and mount on wall, latch side.	Carl Johns	Signs are not room identifiers. "Employees only" "Visitors only" Etc.	20.07	May 2025	
All Light Switches	Mounted 49.5" above ground.	Move to 48".	Carl Johns		20.21	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Service Counter	43" tall. No accessible 36" section.	Install 36" tall and 36" wide section.	Carl Johns		20.22	FY 2027	
Men's Restroom	No accessible stalls.	Renovate to include accessible stall.	Carl Johns		20.17	FY 2027	
Women's Restroom Soap Dispenser	Mounted above shelf, 49" above ground.	Move to 44".	Carl Johns		20.10	September 2025	
Women's Restroom Accessible Stall Rear Grab-Bar	No grab bar.	Install rear grab bar.	Carl Johns		20.11	September 2025	
Women's Restroom Accessible Stall Side Grab-Bar	25″ long, mounted 37″ high.	Replace with 42" bar, 33-36" above ground, extending 54" from back wall.	Carl Johns		20.11	September 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Restroom Accessible Water Closet	Flush control on closed side.	Replace flusher with right-side flusher.	Carl Johns		20.11	FY 2027	

Facility _	Canterbury Equine Center / Parks	Date	6/9/2020	
Contact Pers	son <u>Carl Johns</u>		DepartmentACFM	

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Parking	No Accessible Parking Spaces.	Reconfigure to add accessible parking and access aisle.	Carl Johns		21.01	<b>PARKS DEPT.</b> TBD
Main Office East Entrance	Door threshold is taller than ¼". Entrance mats are not secured to floor.	Replace threshold to add taper. Secure or remove mats.	Carl Johns		21.02 21.03	TBD
Main Office South East Door	Door threshold is taller than ¼".	Replace threshold to add taper.	Carl Johns		21.08	TBD

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Main Office South West Door	Door threshold is taller than ¼".	Replace threshold to add taper.	Carl Johns		21.07	TBD	
Main Office North West Door	Door threshold is taller than ¼".	Replace threshold to add taper.	Carl Johns		21.12	TBD	
Main Building Light Switches	Mounted 50" above ground.	Lower to 48".	Carl Johns		21.04	TBD	
Hallway East Office Door	Doesn't have 18" maneuvering clearance on latch side of door.		Carl Johns	This is a side entrance to the east office. There is an accessible entrance to the east office around the corner.	21.06	TBD	
Hallway Restrooms Door	Doesn't have 18" maneuvering clearance. Signs don't have raised characters and braille, Mounted on door. Closes faster than 5 seconds.	Add automatic opener or remove door.	Carl Johns	This door opens into hallway where men's and women's restroom doors are located.	21.06	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
West Office Service Desk	42" tall, no 17" for forward approach.	Replace or install 36"tall and 36" wide accessible section.	Carl Johns	Currently being used as construction office, not for service counter.	21.10	TBD	
West Office	Copy machine blocks pathway to 18".	Move copy machine or service counter.	Carl Johns		21.11	TBD	
Men's Restroom 1 <sup>st</sup> Vestibule Door.	Door closes faster than 5 seconds. Sign does not have raised characters and braille, is not mounted on wall.	Adjust or replace closer. Replace sign with ADA accessible sign, mounted on wall, latch side of door.	Carl Johns		21.16 21.39	TBD	
Men's Restroom Vestibule	Only 36" between open door to inner door.	Remove vestibule or inner door.	Carl Johns		21.14 21.15	TBD	
Men's Restroom Mirrors	Mounted 52" above ground.	Lower to 40".	Carl Johns	May need to move soap dispenser.	21.17	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Sinks	Pipes underneath aren't insulated.	Install insulation.	Carl Johns		21.18	TBD	
Men's Restroom Stall Door	Coat hook mounted higher than 48". Doesn't have handles on inside. Not self-closing.	Move coat hook to 48". Install handle on inside of stall door. Install stall door closer.	Carl Johns		21.20 21.22	TBD	
Men's Restroom Accessible Water Closet	Mounted 27" from side wall.	Move so centerline of water closet is 16-18" from side wall.	Carl Johns		21.19 21.23	TBD	
Men's Restroom Accessible Stall	Stall is 58" x 58".	Reconfigure to be at least 54"deep, 60"wide.	Carl Johns	Depth is good, needs to be 2" wider.	21.23	TBD	
Men's Toilet Paper Dispenser	Mounted even with accessible water closet.	Move to 7-9" forward of water closet.	Carl Johns		21.53	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Side Grab Bar	Mounted 36.5" above ground.	Move down .5".	Carl Johns		21.23	TBD	
Men's Restroom Rear Grab Bar	No rear grab bars.	Install Rear grab bar.	Carl Johns		21.23	TBD	
Women's Restroom 1 <sup>st</sup> Vestibule Door.	Door closes faster than 5 seconds. Sign does not have raised characters and braille, is not mounted on wall.	Adjust or replace closer. Replace sign with ADA accessible sign, mounted on wall, latch side of door.	Carl Johns		21.24 21.40	TBD	
Women's Restroom Vestibule	Only 36" between open door to inner door.	Remove vestibule or inner door.	Carl Johns		21.25	TBD	
Women's Restroom Mirrors	Mounted 52″ above ground.	Move to 40".	Carl Johns	May need to move soap dispensers.	21.26	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Restroom Sinks	Pipes underneath are not insulated.	Install insulation	Carl Johns		21.27	TBD	
Women's Restroom Paper Towel Dispensers	Mounted 50" above ground.	Move to 48".	Carl Johns		21.28 21.29	TBD	
Women's Restroom Accessible Stall Door	Coat hook higher than 48". Doesn't have handle on inside. Not self- closing.	Move coat hook to 48". Install handle on inside of stall door. Install stall door closer.	Carl Johns		21.30 21.31	TBD	
Women's Restroom Accessible Water Closet	Mounted 27" from side wall. Flusher is on closed side.	Move so centerline of water closet is 16-18" from side wall. Replace with right-side flusher.	Carl Johns		21.32 21.34	TBD	
Women's Restroom Rear Grab Bar	No rear grab bar.	Install rear grab bar.	Carl Johns		21.32	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Restroom Toilet Paper Dispenser	Mounted even with accessible water closet.	Move to 7-9" forward of water closet.	Carl Johns		21.33	TBD	
Women's Restroom Accessible Stall	59.5" depth, 58" Wide	Reconfigure to at least 54" deep, 60" wide.	Carl Johns		21.32	TBD	
Outside Door to Restroom Hallway	Closes in less than 5 seconds. Sign does not have raised characters and braille, is mounted on door.	Adjust or replace door closer. Replace sign with ADA accessible sign. Mount on wall, latch side of door.	Carl Johns		21.41	TBD	
Water Fountains	Spouts are less than 15" from wall. Mounted higher than 36". Require twisting to use.	Replace with new accessible water fountains.	Carl Johns	3 outside water fountains.	21.35 21.36 21.37 21.38	TBD	
East Pavilion Ramp	Handrails are shorter than 34". Doesn't extend 12" past top & bottom. Doesn't have 4" tall barrier.	Replace handrails.	Carl Johns	Hand rails may be updated in current pavilion renovations.	21.42 21.43 21.44 21.45	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
West Pavilion Ramp	Handrails are shorter than 34". Doesn't extend 12" past top & bottom. Doesn't have 4" tall barrier.	Replace handrails.	Carl Johns	Hand rails may be updated in current pavilion renovations.	21.68 21.69 21.70 21.71 21.72	TBD	
Announcer Booth	Stairs to access booth with no handrails.		Carl Johns		21.73	TBD	
Stable Restrooms Path	Path is less than 36" wide. Doesn't lead to other paths or buildings.	Widen Path, create new path.	Carl Johns	Path leads around east side freestanding restrooms building, but not to road, parking or other buildings.	21.67 21.56 21.57	TBD	
Men's Stable Restroom Door	Inside handle is mounted 50" above ground.	Lower to 48".	Carl Johns		21.46	TBD	
Men's Stable Restroom Mirrors	Mounted 54" above ground.	Lower to 40".	Carl Johns		21.74	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Stable Restroom Paper Towel Dispenser	Mounted 52" above ground.	Lower to 48".	Carl Johns		21.47	TBD	
Men's Stable Restroom Sinks	Pipes underneath are not insulated. Requires gripping and twisting to use.	Install insulation. Replace Faucets.	Carl Johns		21.48 21.49	TBD	
Men's Stable Restroom Accessible Stall Door	Coat hook mounted higher than 48". Doesn't have handle on inside. Not self-closing.	Lower coat hook to 48". Install inside handle. Install stall door closer.	Carl Johns		21.50 21.51	TBD	
Men's Stable Restroom Accessible Stall	60" deep, 57" wide.	Reconfigure to be at least 54" deep, 60" wide.	Carl Johns		21.52	TBD	
Men's Stable Restroom Accessible Water Closet	Mounted 27" from side wall.	Move so centerline of water closet is 16-18" from side wall.	Carl Johns		21.52	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Stable Restroom Toilet Paper Dispenser	Mounted even with water closet.	Move to be 7-9" forward of water closet.	Carl Johns		21.53	TBD	
Men's Stable Restroom Rear Grab Bar	No rear grab bar.	Install rear grab bar.	Carl Johns		21.52	TBD	
Women's Stable Restroom Door	Inside handle is mounted 50" above ground.	Move to 48".	Carl Johns		21.59	TBD	
Women's Stable Restroom Mirrors	Mounted 54" above ground.	Move to 40".	Carl Johns		21.61	TBD	
Women's Stable Restroom Paper Towel Dispensers	Mounted 52" above ground.	Move to 48".	Carl Johns		21.60	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Stable Restroom Sinks	Pipes underneath are not insulated. Requires gripping and twisting to use.	Install insulation. Replace faucets.	Carl Johns		21.60 21.62	TBD	
Women's Stable Restroom Stall Door	Coat hook mounted higher than 48". No inside door handle. Not self-closing.	Move coat hook to 48". Install inside door handle. Install stall door closer.	Carl Johns		21.63	TBD	
Women's Stable Restroom Accessible Water Closet	Mounted 27" from side wall. Flusher on closed side.	Move so centerline of water closet is 16-18" from side wall. Replace with right-side flusher.	Carl Johns		21.64	TBD	
Women's Stable Restroom Accessible Stall	55" wide, 59.5" deep	Reconfigure to be at least 54" deep, 60" wide.	Carl Johns		21.64	TBD	
Women's Stable Restroom Toilet Paper Dispenser	Mounted even with accessible water closet.	Move to 7-9" forward of water closet.	Carl Johns		21.65	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Stable Shower Door	Door is less than 32" wide.		Carl Johns	Shower is not accessible.	21.58 21.66	TBD	
Men's Stable Shower Door	Door is less than 32" wide.		Carl Johns	Shower is not accessible.	21.55	TBD	

Facility	Consolidated Communication Center	<b>Date</b> <u>5/1</u>	2/2020
Contact I	Person <u>Carl Johns</u>	Department	ACFM
Email	fjohns@alachuacounty.us	Phone	352-384-3190

Email fjohns@alachuacounty.us

352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Accessible Restrooms: Rear Grab-bars	Rear grab-bars are only 24" long. Should be a minimum of 36" and extend 24" on the open side and 12" on the closed side.	Replace grab-bars with ones that are at least 36″ long.	Carl Johns		22.01 22.03 22.06 22.09	September 2025
Accessible Restrooms: Toilet Paper Dispensers	Toilet paper dispenser is mounted 14" away from the toilets, should be 7-9".	Move toilet paper dispenser so that it is within 7-9" of the toilet.	Carl Johns		22.01 22.03 22.06	September 2025
Accessible Restrooms Water Closet	Mounted 21" away from the side wall, should be 16-18".	Move toilet so that it is 16-18" away from the side wall.	Carl Johns		22.03	FY 2026

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restrooms: Soap Dispensers	Soap dispenser is 49" from the bottom to the floor, should be no more than 48".	Move soap dispenser so that it is 48" to the floor.	Carl Johns		22.16	September 2025	
Van Accessible parking	No van accessible parking sign on the van accessible parking space.	Add a sign that says van accessible to the parking space.	Carl Johns		22.07	May 2025	
Interior Rooms Light Switches	Light switches are higher than 48".	Move light switches down so that they are no more than 48" to the floor.	Carl Johns		22.11	FY 2026	
Main Room Interior Ramp Handrails	Indoor ramp hand railing does not extend at least 12" past the ends of the ramp.	Add railing that extends 12" past the ends of the ramp.	Carl Johns		22.12	FY 2026	
Front Entrance/Lobby Service Counter	Service counter is 42" above the ground, should be no more than 36" tall and at least 36" wide.	Move service counter so that it is no more than 36" above the ground.	Carl Johns		22.14	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom in Lobby: Door Closer	Door closes faster than 5 seconds, should take at least 5 seconds to close.	Adjust door closer so that it takes at least 5 seconds to close.	Carl Johns		22.19	Complete	

Facility	Sheriff's Office	Date <u>5/12/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone 3

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Parking Access Aisle	Access aisle is shorter than 5ft, should be a minimum of 5 ft. wide; no van accessible parking sign.	Adjust accessible parking aisle so that it is at least 5 ft. wide and add van accessible parking sign.	Carl Johns		23.01 23.10	June 2025	
Accessible Restrooms Rear Grab-bars	Rear grab bar is only 19" and other is 24", should be a minimum of 36".	Replace back grab bars with a grab- bars that are at least 36" long.	Carl Johns		23.13 23.23	June 2025	
Interior Room Signs	Characters on room signs are more than 60" to the bottom of the highest character.	Move room signs so that the highest character is no more than 60" to the floor.	Carl Johns		23.14	June 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restrooms Coat Hooks	Coat hooks are higher than 48".	Move coat hooks down so that they are no more than 48".	Carl Johns		23.15 23.16	June 2025	
Accessible Restrooms Mirrors	Mirror is higher than 40″ from the bottom to the floor.	Move mirror down so that it is no more than 40" from the bottom to the floor.	Carl Johns		23.20	June 2025	

Facility	Fire Station HQ	Date <u>5/8/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone 3

352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom in Lobby: Toilet Paper Dispenser	Toilet paper dispenser is more than 9" from the toilet, should be 7- 9" away.	Move toilet paper dispenser so that it is 7-9" away from the toilet.	Carl Johns		24.01	September 2025	
Accessible Restroom in Lobby: Water Closet	Water closet is farther than 18" from the wall, should be 16-18" away from the wall.	Move toilet so that it is less than 18" from the wall.	Carl Johns		24.02	FY 2026	
Back Assembly Room: Wheelchair Spaces	No marked spaces for wheelchairs.	Should have 1 wheelchair space for every 25 seats.	Carl Johns		24.19/24.20	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Bathroom in Lobby: Accessible Symbol	Does not have an accessible symbol on the restroom sign.	Put sign on the restroom door that has an accessible symbol on it.	Carl Johns		24.21	September 2025	
Interior Door to Conference Room	Door is less than 32″ wide.	Adjust doorway so that it is at least 32" wide.	Carl Johns		24.25	FY 2026	
Accessible Restroom in Lobby: Paper Towel Dispenser	Paper towel dispenser is more than 48″ above the floor.	Move paper towel dispenser so that it is no more than 48".	Carl Johns		24.28	September 2025	
Ramp to Main Entrance	Ramp surface does not extend at least 12" beyond the inside of the handrail or have a curb barrier of 4- inch diameter sphere.	Adjust ramp handrails so that the ramp extends 12" beyond the handrails or so that they have a curb barrier of 4 inches.	Carl Johns		24.29	FY 2026	
Building Access: Elevators	No elevators to all of the floors, only main floor is accessible.	May require elevator to access all floors.	Carl Johns		24.36	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Bathroom in Lobby: Door Closer	Door closes faster than 5 seconds.	Adjust door closer so that it takes at least 5 seconds to close.	Carl Johns		24.37	Complete	
Inaccessible Restroom Signs	Do not have signs pointing to the accessible restrooms.	Add signs on inaccessible restrooms directing to the nearest accessible restroom.	Carl Johns		24.38/24.39	September 2025	

Facility       Public Works Warehouse	<b>Date</b> <u>5/18/2020</u>
Contact Person Carl Johns	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Office Doors	Narrower than 32", Handles require gripping and twisting.	Replace handles with accessible hardware. Widen doors.	Carl Johns	Widening doors would require major remodeling.	25.11 25.12 25.13 25.14	FY 2027	
Accessible Entrance	Not marked as accessible.	Install sign indicating an accessible entrance.	Carl Johns		25.01	September 2025	
Non-Accessible Entrances	No signs directing toward accessible entrance.	Install signs indicating direction of accessible entrance.	Carl Johns		25.10	September 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Parking	No van accessible spaces, only 2 accessible spaces for 60 car lot.	Reconfigure parking to add a van accessible space. Should be 3 accessible spaces.	Carl Johns	May need to pave additional path to new accessible lane.	25.02	FY 2027	
Entrance Mat	Not secured to floor.	Secure or remove mat.	Carl Johns		25.04	Complete	
All Light Switches	Mounted 50" above ground.	Move to 48".	Carl Johns		25.05	FY 2027	
Lobby Water Fountain	Water fountain not accessible.	Replace with accessible water fountain. May need to relocate or move other items.	Carl Johns		25.06	January 2026	
Service Counter	Is 41" tall, doesn't have an accessible section.	Remodel to make accessible.	Carl Johns	Service counter and window built into wall. Requires renovation.	25.16	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Entrance Ramp Handrail	Is blocked in two, 2" segments by roof supports.		Carl Johns		25.15	FY 2027	
Women's Restroom Door	Requires more than 5lbs of force to open. Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		25.22	Complete	
Women's Accessible Mirror	Mounted 47" above ground.	Lower to 40".	Carl Johns		25.17	May 2025	
Women's Accessible Water Closet	Flush control on closed side.	Replace with water closet with right side flusher.	Carl Johns		25.21	FY 2027	
Women's Accessible Stall Door	Doesn't have handles on both sides. Not self- closing.	Install handles on both sides. Install door closer.	Carl Johns		25.20	September 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Accessible Stall	Not enough maneuvering room.	Move obstructions between water closet and sink.	Carl Johns		25.18	FY 2027	
Men's Accessible Mirror	Mounted 47" above ground.	Lower to 40".	Carl Johns	May need to relocate soap dispenser.	25.07	January 2026	
Men's Accessible Stall Door	Doesn't have handles on both sides. Not self- closing.	Install handles on both sides. Install door closer.	Carl Johns	Has makeshift bungee door closer using coat hanger. (coat hanger will be moved.)	25.08	September 2025	
Men's Accessible Stall Coat Hook	Mounted 65″ above ground.	Lower to 48"	Carl Johns		25.08	September 2025	
Men's Accessible Water Closet	Flush control is mounted on closed side.	Replace water closet with right side flusher.	Carl Johns		25.09	FY 2027	

Facility	Public Works Fleet Building	<b>Date</b> 5/18/2020
Contact Pe	erson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Pri Date	iority
Accessible Parking	Not located on closest path. No indicated path to building. Must cross parking lot.	Reconfigure parking to be closer to entrance.	Carl Johns	Placed between Main building and fleet. Main building has required spaces in front lot, this is only fleet accessible parking.	26.11 26.13 26.14 26.15	FY 2027	
"Women's" Accessible Restroom.	This is the only accessible Restroom. Not marked accessible, no raised characters or braille.	Make unisex restroom. Replace sign with ADA accessible sign mounted on wall, latch side.	Carl Johns	Men's restroom is not accessible, cannot be converted without major remodeling.	26.02	March 2025	
Accessible Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		26.02	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Paper Towel Dispenser	Mounted 65″ above ground.	Move to 48".	Carl Johns	May need to move soap dispenser and wall mounted metal plate.	26.03	September 2025	
Accessible Restroom Water Closet	Seat is 16" from ground, flush control on closed side.	Replace water closet with seat 17-19", and flusher on right side.	Carl Johns		26.04	FY 2027	
Accessible Restroom Rear Grab Bar	Doesn't have 12" clearance above.	Move the above mounted shelf up to give proper clearance.	Carl Johns		26.04	May 2025	
"Men's" Non- Accessible Restroom Sign	Doesn't point to accessible restroom, have raised characters and braille.	Replace with ADA accessible sign, directional sign, mount on wall, latch side.	Carl Johns	Located in narrow 32" path. (See next item.)	26.12	May 2025	
Path to Break Room	Path is 32" wide.	Widen to 36".	Carl Johns	Would require major remodeling.	26.16 26.12	FY 2027	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Waiting Room / Lobby	No wheelchair spaces.	Move furniture to create wheelchair space.	Carl Johns		26.10	Complete	
Lobby Water Fountain	Fountain is not accessible.	Replace with an accessible fountain, relocate to a place with proper clearance.	Carl Johns		26.09	FY 2026	
Lobby, Entrance, Hallway, Rear Door Mats	Not secured to floor.	Secure or remove mats.	Carl Johns	4 mats: 2 in lobby/entrance, 1 in narrow hall to break room, 1 at narrow rear exit.	26.07 26.08 26.16 26.17	Complete	
All Light Switches	Mounted 50" above ground.	Lower to 48".	Carl Johns		26.06	FY 2027	
Path to Rear Exit	Narrower than 36". Less than 18" maneuvering space on latch side of door.	Rearrange furniture to create space.	Carl Johns		26.17	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Service Counter	No accessible portion of counter.	Replace with counter that has a 36" tall and 36" wide section.	Carl Johns		26.18	FY 2027	

Facility	Public Works Main Building	Date <u>5/12/2020</u>	
Contact Pe	rson <u>Carl Johns</u>	Department ACFM	

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion P Date	riority
Conference Room A South Door	Door knob requires gripping and twisting.	Replace with ADA approved handle.	Carl Johns		27.01	September 2025	
Conference Room B Table	26.5" clearance underneath table.	Raise table .5" (if possible) or replace.	Carl Johns		27.02	FY 2027	
Non-accessible Restrooms	Do not have signs directing towards accessible restrooms.	Install directional signs.	Carl Johns		27.05	September 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Rear Entrance Ramp	Top platform 59" wide. No rail on building side. No barrier at 4" high.	Widen Platform 1". Install rail on building side. Replace handrail to include 4" high barrier.	Carl Johns	May be possible to add 4" high barrier to existing rails.	27.06 27.32 27.33	FY 2027	
Rear Entrance	No sign marking as an accessible entrance.	Install "Accessible Entrance" sign.	Carl Johns		27.07	September 2025	
Side Accessible Entrance	No sign marking as an accessible entrance.	Install "Accessible Entrance" sign.	Carl Johns		27.17	September 2025	
Side Non- Accessible Entrance	No sign directing toward accessible entrances.	Install directional sign.	Carl Johns		27.18	September 2025	
All Room Signs	Baseline of characters is 64" above ground. Most mounted on wrong side of door.	Move so characters are 48-60" above ground. Mount on wall, latch side of door.	Carl Johns		27.19 27.20	January 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Most Office Door Knobs	Require gripping and twisting.	Replace with accessible door hardware.	Carl Johns		27.20	September 2025	
Waiting Room.	No wheelchair spaces designated.	Move furniture to create wheelchair accessible space.	Carl Johns		27.22	September 2025	
Water Fountains	No water fountain for standing persons.	Move shorter water fountain so spout is 38-43" from ground.	Carl Johns	Taller water fountain is currently accessible. Shorter water fountain is too short to be accessible.	27.23 27.24 27.25	FY 2027	
Accessible Restroom Signs	No signs indicating the restrooms are accessible.	Install signs to indicate restrooms are accessible.	Carl Johns		27.03 27.04	May 2025	
Men's Accessible Restroom Door	Door requires more than 5lbs to open, closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		27.04	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Rear Grab Bar	Extends 22" to open side, less than 1.5" clearance underneath.	Replace with proper length bar.	Carl Johns	Sink prevents installing bar to extend 24". Need to move sink. Side and rear bar are 1 piece.	27.10 27.11	FY 2026	
Men's Restroom Side Grab Bar	Mounted 32.5" above ground. 1" clearance underneath.	Move to be 33-36" above ground.	Carl Johns	Side and rear bar are 1 piece. (Needs to be replaced, see above item.)	27.08 27.09	FY 2026	
Men's Restroom Accessible Stall Coat Hook	Mounted 67" above ground.	Move to 48".	Carl Johns		27.12	September 2025	
Men's Restroom Accessible Stall Mirror	Mounted 48" above ground.	Move to 40".	Carl Johns	May require moving soap dispenser.	27.13	May 2025	
Men's Restroom Toilet Paper Dispenser	Mounted 13" forward of water closet.	Move to 7-9" forward of water closet.	Carl Johns		27.16	September 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Accessible Stall Door	Doesn't have handles. Not self- closing.	Install handles on both sides of door. Install door closer.	Carl Johns		27.14 27.15	September 2025	
Women's Accessible Restroom Door	Closes in less than 5 seconds. Requires more than 5lbs of force to open.	Adjust or replace door closer.	Carl Johns		27.04	Complete	
Women's Restroom Accessible Stall Mirror	Mounted 48" above ground.	Move to 40".	Carl Johns	May need to move soap dispenser.	27.27	June 2025	
Women's Restroom Accessible Stall Coat Hook	Mounted 67" above ground.	Move to 48".	Carl Johns		27.30	September 2025	
Women's Restroom Accessible Stall Door	Doesn't have handles on both sides. Not self- closing.	Install handles on both sides. Install door closer.	Carl Johns		27.29 27.30	September 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Restroom Side Grab Bar	Mounted 32.5" above ground. Only 1" clearance underneath.	Move bar up to 33- 36".	Carl Johns	Side and rear bar are 1 piece. (Needs to be replaced, see next item.)	27.28 27.34	January 2026	
Women's Restroom Rear Grab Bar	Only extends 22" to open side. Less than 1.5" clearance underneath.	Replace with proper length bar.	Carl Johns	Sink prevents installing bar to extend 24". Need to move sink. Side and rear bar are 1 piece.	27.31	January 2026	
Women's Restroom Accessible Stall Toilet Paper Dispenser	Mounted 13" forward of water closet.	Move to 7-9".	Carl Johns		27.28	September 2025	
Elevators	No elevator or other access to 2 <sup>nd</sup> floor.		Carl Johns			FY 2027	

Facility Alachua County Jail	Date <u>5/14/2020</u>
Contact Person <u>Carl Johns</u>	Department _ ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone 3

352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Light Switches	Higher than 48".	Move light switches down to 48″.	Carl Johns		28.07	FY 2026
Bond Counter	Taller than 36".	Move counter so that it is no more than 36" above the ground.	Carl Johns		28.18	FY 2026
Accessible Bathroom Door Handles	Door handles not accessible; require twisting of the wrists.	Replace hardware on doors with accessible hardware.	Carl Johns		28.25	September 2025

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Room Signs	No braille or raised characters.	Replace room signs with signs that have raised characters and braille.	Carl Johns		28.47 28.48	September 2025	
Accessible Bathrooms Sink Pipes	Sinks pipes are not insulated.	Insulate sink pipes in accessible bathrooms.	Carl Johns		28.53 28.54	September 2025	
Women's Accessible Restrooms: Soap Dispensers	Soap dispenser higher than 48".	Move soap dispensers down to 48" maximum.	Carl Johns		28.56	September 2025	
Accessible Restroom Stall Doors	Stall door handle not accessible and doors are not self- closing.	Replace stall door hardware with accessible handles and make doors self-closing.	Carl Johns		28.59	FY 2026	
Inaccessible Restroom Signs	No signs indicating where accessible restrooms are.	Put signs directing toward accessible restrooms at inaccessible restrooms.	Carl Johns		28.58	September 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Coat Hooks	Coat hooks taller than 48".	Move coat hooks down to 48".	Carl Johns		28.60	May 2025	
Main Elevator First Floor	Missing tactile star on first floor elevator entrance.	Put a sign with tactile star on elevator first floor sign.	Carl Johns		28.62	February 2025	
Accessible Restroom Toilet Paper	Toiletpaperdispenser is lessthan 7" from toilet.Should be between7 and 9".	Move toilet paper so that it is 7-9" away from toilet.	Carl Johns		28.64	September 2025	
Van Accessible Parking Spaces	Missing van accessible parking signs.	Put van accessible parking signs on van accessible parking spaces.	Carl Johns		28.65	February 2025	
Front Lobby Water Fountain	Water fountain spout higher than 36".	Move water fountain down so that spout is no more than 36".	Carl Johns		28.67	May 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Locker Rooms in Bathrooms: Benches	Benches are only 9" deep, should be 20- 24" deep and have some back support or be affixed to a wall.	Replace benches with new benches that are 20-24" deep with back support.	Carl Johns		28.73	FY 2026	
Women's Accessible Restroom: Flush Control	Flush control is located on the closed side, should be on the open side.	Move flush control to opposite side of toilet.	Carl Johns		28.75	May 2025	
Entrance to Female Pods: Door Closer	Door closer is faster than 5 seconds.	Adjust door closer so that it takes at least 5 seconds to close.	Carl Johns		28.76	Complete	
Front Service Counter	Service counter is only 25.5" wide, should be at least 36" wide.	Rearrange front service counter so that a portion of it is at least 36" wide and no more than 36" tall.	Carl Johns		28.78	FY 2026	
Jail Cells Accessibility	Less than 5% of the cells are ADA accessible.	Adjust cells so that at least 5% are ADA accessible.	Carl Johns			FY 2026	

Facility	Fire Station 20	Date <u>5/20/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Main Entrance Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns	2021	29.04	Complete
Accessible Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns	2021	29.03	Complete
Accessible Restroom Water Closet	Flush Control on closed side.	Replace water closet with right side flush control.	Carl Johns		29.01	FY 2026

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Rear Grab Bar	Grab bar shorter than 36".	Replace with 36" grab bar.	Carl Johns		29.01	April 2025	
Accessible Restroom Side Grab Bar	Grab bar extends 43" from rear wall.	Move bar 12" from rear wall.	Carl Johns	Grab bar proper length, needs to be 12" from rear wall.	29.01	April 2025	
Accessible Restroom Toilet Paper Dispenser	Mounted less than 7" from water closet.	Move to 7-9" from front of water closet.	Carl Johns		29.01	April 2025	

Facility Fire Station 23	Date <u>5/13/2020</u>
Contact Person Carl Johns	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Main Entrance Mat	Not secured to floor.	Secure or remove mat.	Carl Johns		30.01	Complete
Main Entrance Door	Door closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		30.12	Complete
Men's Restroom Soap Dispenser	Mounted over counter, 48" above ground.	Move to 44" above ground, over counter.	Carl Johns	No soap dispenser in men's accessible stall.	30.02	July 2025

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Sink	Pipes are not insulated.	Install insulation.	Carl Johns		30.03	January 2025	
Men's Restroom Sign	Does not have raised characters and braille. Mounted on door.	Replace with ADA approved sign, mount on wall latch side of door.	Carl Johns		30.05	May 2025	
Men's Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		30.05	Complete	
Men's Restroom Rear Grab Bar	Extends 20 inches from center of water closet to open side.	Move 4 inches to left.	Carl Johns	Bar is proper length. Sink needs to be moved for clearance. 8 Inches of clear space to move sink.	30.04 30.19	May 2025	
Men's Restroom Side Grab Bar	Extends 45" from rear wall.	Move forward 12" from rear wall, so that is extends 54" from rear wall.	Carl Johns	Bar is proper length.	30.06	May 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Accessible Stall Door	Does not have handles on both sides and is not self-closing.	Install handle on inside of stall door and door closer.	Carl Johns		30.07	June 2025	
Women's Restroom Sign	Doesn't have raised characters and braille. Mounted on door.	Replace with ADA approved sign, mount on wall latch side of door.	Carl Johns		30.09	June 2025	
Women's Restroom Door	Closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		30.09	Complete	
Women's Restroom Sink	Pipes underneath are not insulated.	Install insulation.	Carl Johns		30.11	January 2025	
Women's Soap Dispensers.	Mounted above sink and counter, 48" above ground.	Move dispensers to be 44" above ground, over counter.	Carl Johns	May also reposition above open ground and mount at 48".	30.10 30.15	January 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Restroom Paper Towel Dispenser.	Mounted 53″ above ground, over counter.	Move to be 44" above ground, over counter.	Carl Johns	May also reposition above open ground and mount at 48".	30.10	June 2025	
Women's Restroom Rear Grab Bar	Extends 20 inches from center of water closet to open side.	Move 4 inches to right.	Carl Johns	Bar is proper length. Sink needs to be moved for clearance. 8 Inches of clear space to move sink.	30.15 30.18	June 2025	
Women's Restroom Side Grab Bar	Extends 45" from rear wall.	Move forward 12" from rear wall, so that is extends 54" from rear wall.	Carl Johns	Bar is proper length.	30.15	June 2025	
Women's Restroom Accessible Water Closet	Mounted 19" from side wall. Flush control on closed side.	Move so centerline of water closet is 16-18" from side wall. Replace flusher with right side flush control.	Carl Johns		30.08 30.15	FY 2026	
Women's Restroom Toilet Paper Dispenser	Mounted directly next to water closet.	Move to be 7-9" forward of water closet.	Carl Johns		30.08 30.15	June 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Restroom Accessible Stall Door	Doesn't have handles on both sides and is not self-closing.	Install handle on inside of stall door. Install door closer.	Carl Johns		30.13 30.14	March 2025	
Women's Restroom Coat Hook	Mounted 63" above ground.	Move to 48".	Carl Johns		30.13	March 2025	

Facility	Fire Station 24	Date <u>5/13/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department <u>ACFM</u>

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Path from Accessible Parking to Main Entrance	Path has become uneven.	Regrade pathway to even out.	Carl Johns	Already marked out with cones and yellow paint.	31.07	May 2025	
Main Entrance Door	Door closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		31.03	Complete	
Room Signs	Baseline of character is 62″ above ground.	Lower signs so characters are 48- 60″.	Carl Johns		31.04	May 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Light switches	Switches mounted higher than 48"	Relocate switches.	Carl Johns	Many but not all switches are above 48".	31.05 31.06	FY 2026	
Accessible Restroom Stall Door	Doesn't have handles on inside of door.	Install handle.	Carl Johns		31.02	Oct 2025	
Accessible Restroom Door	Door handle mounted 50" above ground.	Move handle to 48"	Carl Johns	May need to move lock or replace door.	31.01	Oct 2025	

Facility	Fire Station 25	Date <u>5/20/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department <u>ACFM</u>

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Pr Date	riority
Accessible Entrance Mat	Mat not secured to floor.	Secure or remove mat.	Carl Johns		32.01	Complete	
Accessible Entrance	Closes in less than 5 seconds. Less than 18" maneuvering space next to door handle.	Adjust or replace door closer. Extend porch for maneuvering space.	Carl Johns		32.02	Complete	
Right-Side Restroom Coat Hook	Mounted 65" above ground.	Move to 48".	Carl Johns		32.07	Oct 202 5	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Right-Side Restroom Paper Towel Dispenser	Mounted 52" above ground.	Move to 48".	Carl Johns		32.08	Oct 2025	
Left-Side Restroom Paper Towel Dispenser	Mounted 52" above ground.	Move to 48".	Carl Johns		32.09	Oct 2025	

Facility	Fire Station 30	Date <u>5/14/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Restroom Coat Hook	Mounted 68" above ground.	Move to 48".	Carl Johns		33.06	Nov 2025	
Women and men's Paper Towel Dispensers	Mounted 50" above ground.	Move to 48".	Carl Johns		33.18	Nov 2025	
Women's Water Closet	Flush control on closed side.	Replace with right- side flusher.	Carl Johns		33.14	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Sink	Pipes underneath are not insulated.	Install insulation.	Carl Johns		33.12	January 2025	
Men's Stall Door	Doesn't have handles on both sides. Not self- closing.	Install handles on both sides of stall door. Install stall door closer.	Carl Johns		33.08 33.09 33.11	January 2025	

Facility Fire Station 33	Date <u>5/20/2020</u>
Contact Person <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Front Entrance Door	Door closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		34.07	Complete	
Living Room Door	Handles are 49″ above ground.	Replace door so that handle is 48" max.	Carl Johns		34.05	Nov 2025	
Accessible Restroom Coat Hook	Mounted 63″ above ground.	Move to 48".	Carl Johns		34.02	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Toilet Paper Dispenser	Mounted 11" from front of water closet.	Move to be 7-9".	Carl Johns		34.04	Nov 2025	
Rear (North) Entrance.	1" lip between pathway and door.	Bevel lip.	Carl Johns		34.06	Nov 2025	

Facility Fire Station 40	Date <u>5/19/2020</u>
Contact Person Carl Johns	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Accessible Restroom Mat	Mat is not secured to floor.	Secure or remove mat.	Carl Johns		35.01	Complete
Accessible Parking Space.	No marked access aisle.	Reconfigure parking for an access aisle	Carl Johns		35.02	FY 2026
Accessible Restroom Sink	Pipes under sink are not insulated.	Install insulation.	Carl Johns		35.03	January 2025

Facility Fire Station 41	Date <u>5/21/2020</u>
Contact Person <u>Carl Johns</u>	Departmen1t ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Mirror	Mirror mounted 41" from reflective surface to ground.	Move to be 40" max.	Carl Johns		36.02	Nov 2025	
Main Entrance	Entrance mat not secured to floor.	Secure or remove mat.	Carl Johns		36.03	Complete	

Facility _	Fire Station 60	Date <u>5/21/2020</u>
Contact Per	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priority Date
Parking	No marked accessible parking spaces.	Reconfigure parking to include 1 van accessible space, access aisle and sign.	Carl Johns		37.08	FY 2026
Parking	Running slope of path greater than 1:20″	Regrade or replace with proper curb ramp.	Carl Johns		37.09	FY 2026
Main entrance	Door closes faster than 5 seconds, entrance mats not secured.	Adjust or replace door closer. Secure mats to floor.	Carl Johns		37.01	Complete

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Hallway door	10" maneuvering space on handle side of door.	Remove door or remodel to create 18" of maneuvering clearance.	Carl Johns	Separates front from bunks and restrooms.	37.07	May 2025	
Men's Restroom Mirror	Mounted 43" above ground to reflective surface.	Move mirror to be 40" from ground.	Carl Johns	Soap dispenser and 2 power outlets in way. May need to replace with 2 smaller mirrors.	37.02	May 2025	
Men's Restroom Accessible Stall Door	Doesn't have inside handle, coat hook mounted 63" above ground.	Install handle on inside, remount coat hook at 48".	Carl Johns		37.04 37.05	May 2025	
Men's Restroom Accessible Water Closet.	Mounted 20" from side wall.	Move to be 16-18" from side wall to center of water closet.	Carl Johns		37.03	FY 2026	
Men's Restroom Side Grab Bar	Extends 46" from rear wall.	Move bar to be 12" away from rear wall so that it extends 54".	Carl Johns	Bar is long enough, should be mounted 12" from rear wall.	37.03	Nov 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Sinks	Pipes under sinks are not insulated.	Install insulation.	Carl Johns	2 sinks	37.06	January 2025	
Men's Restroom Sign	Doesn't have raised, contrasting characters, braille, and is mounted 61" on door.	Replace with accessible sign, mount 48-60" on wall, latch side.	Carl Johns		37.13 37.14	August 2025	
Women's Restroom Sign	Doesn't have raised, contrasting characters, braille, and is mounted 61" on door.	Replace with accessible sign, mount 48-60″ on wall, latch side.	Carl Johns		37.15	August 2025	
Women's Restroom Sink	Pipes under sink aren't insulated.	Install insulation.	Carl Johns		37.11	January 2025	
Women's Water Closet	Mounted 20" from side wall.	Move to be 16-18" from center of water closet to side wall.	Carl Johns		37.10	FY 2026	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Side Grab Bar	Extends 46" from rear wall.	Move bar to be 12" away from rear wall so that it extends 54".	Carl Johns	Bar is long enough, should be mounted 12" from rear wall.	37.10	Nov 2025	

Facility       Fire Station 80 (Old)	Date <u>5/13/2020</u>
Contact Person <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion P Date	Priority
Accessible Parking	Accessible Parking Sign shorter than 60".	Replace Accessible parking sign mount.	Carl Johns	May need to be moved when reconfiguring parking.	38.01	Nov 2025	
Accessible Parking	Accessible parking space is not van accessible and has no access aisle.	Reconfigure parking spaces.	Carl Johns	May need to pave additional pathway for accessible parking aisle.	38.02	FY 2026	
Main Entrance Door	Door closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		38.07	Complete	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Sign	Sign is mounted on door. Does not have braille, raised and contrasting characters.	Replace sign. Mount on wall next to door, latch side.	Carl Johns	Convert to accessible unisex restroom. Install accessible sign.	38.05	August 2025	
Men's Restroom Door	Restroom door handle requires gripping and twisting to open.	Replace with ADA approved handle.	Carl Johns		38.05	August 2025	
Men's Restroom Door	Restroom door closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		38.05	Complete	
Men's Restroom Coat Hooks	Coat hooks are mounted higher than 48″.	Remount coat hooks at 48".	Carl Johns	3 coat hooks: 2 mounted on wall 1 mounted on stall door	38.06 38.10 38.11	August 2025	
Men's Restroom Sinks	Pipes under sinks are nor insulated.	Install insulation.	Carl Johns	2 sinks	38.09	January 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Stall	Accessible stall less than 60" wide, door not self-closing, doesn't have handles on both sides.	Reconfigure Stall walls, include stall door closer and handles on both sides of door.	Carl Johns	May require removal of urinal.	38.06 38.14	FY 2026	
Men's Restroom Water Closet	Water closet mounted more than 18" from side wall.	Remount water closet so centerline is 16-18" from side wall.	Carl Johns	Currently mounted 20" from side wall.	38.06	FY 2026	
Unisex Restroom Sign	Sign is not mounted on wall, latch side.	Remount sign on wall, latch side.	Carl Johns		38.04	May 2025	
Unisex Restroom Water Closet	Water closet doesn't have 60" width clearance.	Remodel restroom to move block wall, and reconfigure or remove shower.	Carl Johns	May remodel men's restroom to be unisex accessible and make this restroom non- accessible.	38.03 38.12 38.13	FY 2026	
Unisex Restroom Sink	Pipes under sink are not insulated.	Install insulation.	Carl Johns	May not be required if made into non- accessible restroom.	38.08	January 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Unisex Restroom Toilet Paper Dispenser	Dispenser mounted 10" from front of water closet.	Remount 7-9" from front of water closet.	Carl Johns	May not be required if made into non- accessible restroom.	38.03	Oct 2025	
Unisex Restroom Water Closet	Water closet seat 20" above floor, flush control on closed side.	Replace with accessible water closet that is 17-19" and flush control on right side.	Carl Johns	May not be required if made into non- accessible restroom.	38.03	Oct 2025	
Unisex Restroom Door	Restroom door closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns	May not be required if made into non- accessible restroom.	38.04	Complete	
Unisex Restroom Door	Restroom door handle requires gripping and twisting to open.	Replace with ADA approved handle.	Carl Johns	May not be required if made into non- accessible restroom.	38.04	Nov 2025	

Facility	Fire Station 81	Date <u>5/13/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department <u>ACFM</u>

Email fjohns@alachuacounty.us Phone

352-384-3190

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Pathway to Main Entrance from Accessible Parking	Pathway pads are not even, creates large bump in pathway.	Grade pathway.	Carl Johns	Should be able to grind down higher pathway pad.	39.01	FY 2026	
Main Entrance Door	Door closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		39.03	Complete	
Accessible Restroom Sink	Pipes under sink are not insulated.	Install insulation.	Carl Johns		39.04	January 2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Rear Support Bar	Rear support bar does not extend 24 inches from center of water closet to open side.	Replace rear grab bar.	Carl Johns	Rear and side grab bar are one unit, must replace with another "combo" or 2 pieces.	39.05 39.06	Nov 2025	

FacilityFire Station 82Date	te <u>5/13/2020</u>
Contact Person <u>Carl Johns</u> De	partment ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone <u>352-384-3190</u>

Target Person Solution **Photo Completion Priority** Access Issue Comments Area Responsible Date Accessible Dispenser mounted Remount toilet Carl Johns 40.1 Restroom Toilet too close to water paper dispenser 7-Paper Dispenser 9" from front of closet. July 2025 water closet. Accessible Pipes under sink are Install covers. Carl Johns 40.03 Restroom Sink not covered. January 2025 Accessible Dispenser Mounted Remount dispenser Carl Johns 40.04 **Restroom Paper** higher than 48". with operable parts at 48". **Towel Dispenser** Dec 2025

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Rear Grab Bar	Rear grab bar is less than 36″ long.	Replace with bar at least 36″ long.	Carl Johns	Needs to extend from center of water closet: 12" to closed side 24" to open side	40.05 40.06	Dec 2025	
Accessible Restroom Flush Control	Flush Control is located on closed side.	Replace water closet with flush control on right side.	Carl Johns		40.07	Dec 2025	
Accessible Restroom Door	Restroom door closes in less than 5 seconds.	Adjust or replace door closer.	Carl Johns		40.08	Complete	
Accessible Restroom Coat Hook	Coat hook mounted higher than 48".	Remount coat hook at 48".	Carl Johns		40.08	Dec 2025	
Front Counter	Front Counter does not have a section that is accessible.	Add or replace counter that has section that is 36" tall and wide.	Carl Johns		40.09	FY 2026	

Facility Cope	eland Park / Parks Dept.	Date <u>5/29/2020</u>
Contact Person	Carl Johns	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Route to Pavilion from Accessible Parking	No accessible paved route to the pavilion.	Add a sidewalk that goes from the accessible parking to the pavilion.	Ed Williams	Site improvement project underway (in A&E phase).	41.10 41.14	2025	
Right Restroom Rear Grab-bar	Rear grab-bar extends 20" on the open side of the water closet, should be at least 24". Less than 1.5" of clearance under rear grab-bar.	Move rear grab-bar over so that it extends at least 24" on the open side of the water closet, may need to move sink in order to make room. Move objects so that there is 1.5" of clearance under rear grab-bar.	Carl Johns		41.02 41.03	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Right Restroom Toilet Paper Dispenser	Toilet paper dispenser is only 4" away from toilet, should be 7-9".	Move toilet paper dispenser so that it is 7-9" away from the toilet.	Carl Johns		41.22	TBD	
Right Restroom and Left Restroom: Thresholds	Threshold is ¾" and not beveled. Must be no more than ¼" or be beveled.	Adjust threshold so that it is no more than ¼".	Carl Johns		41.04	TBD	
Right Restroom and Left Restroom: Soap Dispensers	There are no soap dispensers in both restrooms.	Add soap dispensers that are 48" above the ground.	Carl Johns		41.17	TBD	
Left Restroom Rear Grab-bar	Less than 1.5" of clearance below rear grab-bar of lest restroom water closet.	Move objects below grab-bar so that there is at least 1.5" of clearance.	Carl Johns		41.08 41.09	TBD	
Left and Right Restroom Signs	Signs do not have raised characters or braille, and are not mounted on the latch side of the wall.	Get new restroom signs that have raised characters and braille and mount them on the latch side of the door.	Carl Johns		41.15	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Pavilion Tables	Top of the tables at the pavilion are 27" and only have 25" of clearance underneath. Should be 28-34" tall and have at least 27" of clearance underneath.	Replace tables with new ones that are 28-34" tall and have 27" of clearance underneath.	Carl Johns		41.19	TBD	
Left Restroom: Flush Control	The flush control is located on the closed side of the water closet.	Move flush control so that it is located on the open side of the water closet.	Carl Johns		41.07	TBD	

Facility _	Cynthia Moore Chestnut Park / Parks Dept.	Date <u>5/29/2020</u>
Contact Per	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion P Date	Priority
Men and Women's Restroom Signs	Signs do not have raised characters or braille, and are not mounted in the latch side of the door.	Replace signs with signs that have braille and raised characters, and mount them on the latch side of the door.	Carl Johns		42.04	TBD	
Men and Women's Restroom Door Closers	Door requires more than 5lbs of force to open and closes in less than 5 seconds.	Adjust door or replace door so that it requires less than 5 lbs. of strength to open and adjust the door closer so that it takes at least 5 seconds to close.	Carl Johns	Only left restroom door closer is faster than 5 seconds.	42.15 42.20	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men and Women's Toilet Paper Dispensers	Toilet paper dispenser is not 7- 9" away from the toilet.	Move the toilet paper dispenser so that it is 7-9" away from the toilet.	Carl Johns		42.17 42.22	TBD	
Men and Women's Mirrors	Missing mirrors.	Put mirrors in the restroom that are mounted no more than 40" above the ground.	Carl Johns	May not be required.	42.18 42.23	TBD	
Men and Women's Soap Dispensers	Soap dispensers are higher than 48″ above the ground.	Move soap dispensers so that they are no higher than 48" above the ground.	Carl Johns		42.19 42.21	TBD	
Pavilion Tables	Table surface extends 6.5" off the side of the table, it should extend 17- 25" off the edge so that there is accessible knee space.	Replace tables or adjust tables so that the edge extends 17-25" off the side of the table.	Ed Williams	2 new pavilions w/ accessible tables were installed in 2021.	42.08	2021	

Facility _	Earl P. Powers Park / Parks Dept.	Date <u>5/19/2020</u>
Contact Per	son <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Route to Pavilion	No paved or accessible route to the pavilion.	Add an accessible walkway that leads from the accessible parking to the pavilion.	Carl Johns		43.04	TBD	
Men and Women's Restrooms: Sink Pipes	Pipes below the sinks are not insulated.	Insulate pipes below sinks.	Ed Williams	Corrected	43.05 43.11	TBD	
Men and Women's Soap dispensers	No soap dispensers in accessible stalls, other soap dispensers are more than 48" tall.	Either add accessible soap dispensers in the accessible stalls or adjust the other soap dispensers so that they are no more than 48" to the ground.	Ed Williams	Corrected	43.05 43.07 43.11 43.13	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men and Women's Restroom Signs	Restroom signs for men and women's bathrooms are faded and the text does not contrast with the background.	Replace signs with new signs that are not faded so that the text contrasts with the background.	Carl Johns		43.06 43.12	TBD	
Men and Women's Bathroom Thresholds	Both Women and Men restroom thresholds are almost 1" tall with no bevels, they should be no taller than ¼".	Adjust thresholds of both restrooms so that they are no taller than ¼" or are beveled.	Carl Johns		43.08 43.09	TBD	
Men's Toilet Paper Dispenser	Men's toilet paper dispenser is 11" from the toilet, it should be 7-9" away.	Move toilet paper dispenser so that it is 7-9" away from the toilet.	Carl Johns		43.10	TBD	
Men and Women's Accessible Restrooms: Stall Doors	Men and women's stall doors are not self-closing and do not have handles on both sides.	Adjust stall doors so that they are self- closing and add handles to both sides.	Carl Johns		43.15 43.16 43.17 43.18	TBD	
Men and Women's Restrooms: Accessible Stall Side Grab-bars	Men and women's accessible side grab-bars are more than 12" from the rear wall.	Move both grab-bars so they are 12" from the rear wall, and extend 54" beyond the rear wall.	Ed Williams	Corrected	43.19 43.20	TBD	8

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Water Fountain	Water fountain spout is 38" above the ground, should be no more than 36" above the ground.	Move water fountain down so that the spout is no more than 36" above the ground.	Ed Williams	Corrected	43.14	TBD	
Men and Women's Restrooms: Door Closers	Men and women's restroom doors close faster than 5 seconds.	Adjust both door closers so that the door takes at least 5 seconds to close.	Carl Johns		43.12	TBD	

Facility Kanapaha Botanical Gardens	Date <u>5/22/2020</u>
Contact Person Carl Johns	Department ACFM
Email <u>fjohns@alachuacounty.us</u>	<b>Phone</b> 352-384-3190

Target Person Solution **Photo Completion Priority** Access Issue Comments Area Responsible Date Women's Flush control is Move the flush Carl Johns 44.05 TBD Accessible Stall: located on the control so that it is closed side of the located on the open Flush Control side of the water water closet. closet. Women's The accessible stall Adjust the stall door Carl Johns 44.11 TBD Accessible Stall so that it is selfdoor is not selfclosing. Door closing. Lobby Service Adjust the service Carl Johns The service counter 44.09 TBD is taller than 36". counter at the main Counter entrance so that a portion of it is no more than 36" tall and at least 36" long.

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Parking Sign	The accessible parking sign is less than 60" above the ground.	Adjust the parking sign so that the bottom of the sign is at least 60" to the ground.	Carl Johns		44.10	TBD	
Water Fountain at the Restrooms	The water fountain spout is more than 36" to the ground.	Move the water fountain so that the spout is no more than 36" to the ground.	Carl Johns		44.12	TBD	
Men's Restroom Accessible Water Closet	Located 19" from side wall.	Move so the centerline of water closet is 16-18" from side wall.	Carl Johns		44.18	TBD	
Men's Restroom Accessible Stall Door	Not self-closing, doesn't have handles on inside, doesn't have 18" clearance on pull side.	Install door closer, install inside handle.	Carl Johns	Maneuvering clearance is blocked by sinks. There is free space to maneuver under sink counter.	44.20 44.21 44.22	TBD	
Men's Restroom Hand Dryer	Hand dryer is located within swing of restroom entrance door.	Relocate or install new accessible hand dryer.	Carl Johns	Paper towel dispensers are not in use. No hand dryer in accessible stall.	44.15 44.16 44.17	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Women's Restroom Hand Dryer	Hand dryer is located within swing of restroom entrance door.	Relocate or install new accessible hand dryer.	Carl Johns	Paper towel dispensers are not in use. No hand dryer in accessible stall.	44.07	TBD	

Facility	Jonesville Rotary Park	Date <u>5/21/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Tennis Courts and Soccer Fields: Women's Coat Hooks	Coat hook in accessible stall is higher than 48", should be no more than 48" tall.	Move coat hook down so that it is no more than 48" above the ground.	Carl Johns		45.12 45.31	TBD	
Soccer and Baseball Fields: Concession Stand Service Counters	Service counters are 42", should be no taller than 36" and at least 36" long.	Move service counters so that a portion is no taller than 36" and at least 36" long.	Carl Johns		45.13	TBD	
Light Switches	The light switches in the restrooms are 50" tall, should be no more than 48" to the ground.	Move light switches down so that they are no more than 48" to the ground.	Carl Johns		45.15 45.16	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Soccer Fields: Bathroom Mirror	Bathroom mirror is 43" tall, should be no more than 40" from the bottom to the ground.	Move mirror down so that the bottom is no more than 40" to the ground.	Carl Johns		45.17	TBD	
All Accessible Restroom Stall Doors	The accessible stall doors are not self- closing and do not have handles on both sides.	Adjust the accessible stall doors so that they are self-closing and add handles to both sides of the stall doors.	Carl Johns		45.04 45.18 45.35 45.36	TBD	
Tennis Courts and Soccer Fields: Soap Dispensers	Missing soap dispensers.	Add soap dispensers that are no more than 48" to the ground.	Carl Johns		45.19	TBD	
Baseball Fields: Paper Towel Dispenser	Paper towel dispenser is 56" tall, should be no more than 48" to the ground.	Move paper towel dispenser so that it is no more than 48" above the ground.	Carl Johns		45.20	TBD	
Accessible Parking Sign	No van accessible parking sign at the van accessible parking spaces.	Add a sign that says van accessible at the van accessible parking spaces.	Carl Johns		45.21	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Tennis Courts: Men's and Women's Restroom Side Grab-bars	Side grab-bar is only 36" long, should be at least 42".	Replace side grab- bar with one that is 42″ long & extends 54″ from rear wall.	Carl Johns		45.25 45.28 45.32 45.33	TBD	
Tennis Courts: Men's and Women's Restroom Rear Grab-bars	Doesn't have at least 1 ½" of clearance underneath.	Move rear grab-bar so there is at least 1 ½" of clearance underneath.	Carl Johns		45.14 45.32	TBD	
Baseball Fields: Curb Ramp	The curb ramp from accessible parking is steeper than 1:12, it should be no steeper than 1:12.	Adjust curb ramp so that the slope is no steeper than 1:12.	Carl Johns		45.22	TBD	
Tennis Pro Shop Entrance Door	Closes faster than 5 seconds.	Adjust or Replace Door Closer	Carl Johns		45.38	TBD	

Facility <u>S</u>	Santa Fe Lake Park	Date <u>5/26/2020</u>
Contact Pers	on <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone 3

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion P Date	Priority
Accessible Parking Space	No access aisle at the accessible parking space.	Add an access aisle that is at least 5ft wide next to the accessible parking space.	Ed Williams	Corrected	46.01	TBD	
2 <sup>nd</sup> Pavilion: Access Path	There is no accessible path leading to the pavilion.	Add a paved pathway that is accessible leading to the pavilion.	Ed Williams	Corrected	46.04	TBD	
Tables at the Pavilion	Not at least 27" of clearance under the tables for knee space.	Adjust or replace tables so that at least 5% of seating is accessible for wheelchairs.	Ed Williams	Replace 3 tables. Corrected	46.05	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Van Accessible Parking	Van accessible parking space does not have a van accessible parking sign or the symbol of accessibility.	Add a van accessible parking sign and the international symbol of accessibility to the van accessible parking space.	Ed Williams	Corrected	46.06	TBD	
Restroom Threshold	The thresholds at the restrooms are more than ¼". If the threshold is more than ¼" it must be beveled.	Make thresholds no more than ¼" or beveled so that the restrooms are easily accessible.	Carl Johns		46.07	TBD	
Restrooms not Accessible	Both bathrooms need multiple adjustments in order to make each accessible.	Need to add grab bars, widen the accessible stalls, move toilet paper dispensers etc.	Ed Williams	New restroom bldg was completed in March 2024. Old restrooms were demolished.	46.08 46.03	TBD	

Facility Lochloosa Park	Date <u>5/21/2020</u>
Contact Person <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Phone

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Priorit Date
Accessible Parking	Accessible parking and access aisle not marked, on grass. Accessible parking sign is less than 60" from the bottom to the ground.	Mark an access aisle in order to discourage parking there, must be at least 5 ft. Adjust the parking sign so that it is at least 60" to the ground.	Carl Johns		47.01	TBD
Men and Women's Restroom Mirrors	No mirrors in either men or women's restrooms.	Add mirrors that are no more than 40" above the ground.	Carl Johns	May not be required to have mirrors.	47.02 47.07	TBD
Men's Restroom Water Closet	Toilet is 20" from the wall, should be 16-18".	Move toilet so that it is 16-18" from the wall.	Carl Johns		47.03	TBD

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Restroom Grab-bars	Side grab-bar does not extend at least 54" from the rear wall and there is no back grab-bar.	Adjust side grab-bar so that it extends at least 54" beyond the rear wall and add a rear grab bar that is at least 36" long.	Ed Williams	Corrected	47.03	TBD	
Men's Restroom Flush Control	Flush control is located on the closed side of the water closet, should be on the open side.	Move flush control so that it is located on the open side of the water closet.	Carl Johns		47.03	TBD	
Restroom Signs	Both men and women restroom signs do not have braille.	Replace restroom signs with ones that have braille on them.	Carl Johns		47.11 47.12	TBD	
Restroom Door Closers	Men and women's restroom doors close faster than 5 seconds.	Adjust door closers so that both doors take at least 5 seconds to close.	Carl Johns		47.13 47.14	TBD	
Men and Women's Restroom Thresholds	Both thresholds are more than ¼" and not beveled. Must be no more than ¼" or beveled.	Bevel door thresholds to make accessible.	Carl Johns		47.05 47.06	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Route to Restrooms	There is no accessible pathway to the restrooms.	Make a paved pathway that is accessible leading from the accessible parking to the restrooms.	Carl Johns		47.04	TBD	
Women's Toilet Paper Dispenser	Toilet paper dispenser is more than 9" from the toilet, should only be 7-9" away.	Move toilet paper dispenser so that it is 7-9" away from the toilet.	Carl Johns		47.10	TBD	
Women's Restroom Rear Grab-bar	Women's rear grab- bar does not extend 24" on the open side of the water closet.	Move rear grab-bar so that it extends at least 24" on the open side of the water closet and 12" on the closed side.	Carl Johns	Side and rear grab bars are 1 piece.	47.09	TBD	

Facility       Marjorie K. Rawlings Park		Date <u>5/21/2020</u>
Contact Per	son <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

**Phone** 35

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Parking	No marked parking spaces or access aisles, parking is on dirt.	Make a paved accessible parking space that has a marked access aisle at least 5 ft. wide.	Ed Williams	Site improvement project underway (in A&E phase).	48.01	2025	
Men and Women's Restrooms: Sink Pipes	Sink pipes are not insulated.	Insulate sink pipes in men and women's restrooms.	Carl Johns		48.08	TBD	
Route to Pavilions and Tables at the Pavilions	No accessible route to the pavilions. Tables at the pavilions cannot be accessed in a wheelchair.	Create accessible pathway from the accessible parking to pavilions. Replace tables at pavilion so at least 5% of seating is accessible.	Ed Williams	Site improvement project underway (in A&E phase).	48.11 48.12	2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Restroom Signs	Restroom signs do not have braille or raised characters and are not located on the latch side of the door. Signs should also be no higher than 60" to the baseline of the highest character.	Replace signs with ones that have raised characters and braille and are located on the latch side of the door no higher than 60".	Carl Johns		48.14	TBD	
Water Fountain	Spout is only 10" away from the wall, it should be at least 15" from the wall.	Replace water fountain with one that extends far enough from the wall so that the spout is 15" away from the back wall.	Carl Johns		48.17	TBD	
Women's Sink Handles	Not operable without twisting of the wrists.	Replace sink handles with ones that are operable without requiring twisting of the wrists.	Carl Johns		48.18	TBD	
Men and Women's Restroom Water Closets	Farther than 18" from the wall, should be 16-18" away from the side wall.	Move water closets so that they are 16- 18" away from the side wall.	Carl Johns		48.04 48.19	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Flush Control in Women's Restroom	Women's flush control is located on the closed side of the water closet.	Move flush control so that it is on the open side of the water closet.	Carl Johns		48.19	TBD	
Men and Women's Restrooms: Rear grab-bars	Rear grab-bars do not extend at least 24" on the open side of the water closet.	Adjust grab-bars so that they extend at least 24" on the open side of the water closets.	Carl Johns		48.04 48.19	TBD	
Women's Restroom: Side Grab-bar	Side grab-bar does not extend at least 54" from the rear wall.	Adjust side grab-bar so that it extends at least 54" from the rear wall.	Carl Johns		48.20	TBD	
Women's Soap Dispenser	No soap dispensers in the women's restroom.	Add soap dispenser that is no more than 48" above the ground.	Carl Johns		48.21	TBD	
Men and Women's Restrooms: Stall Doors	Do not have handles on both sides. Not self-closing.	Adjust stall doors so that they are both self-closing and add handles to the insides of the stall doors.	Carl Johns		48.06 48.07 48.22	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men and Women's Restroom: Doors	Both doors are heavier than 5 lbs., men's gets stuck in the door frame.	Replace or adjust doors so that it takes less than 5lbs. of force to open.	Carl Johns		48.24 48.25 48.26	TBD	
Accessible Route to Restrooms	No accessible route to the restrooms, only path is dirt.	Create and accessible paved pathway to the restrooms from the accessible parking.	Ed Williams	Site improvement project underway (in A&E phase).	48.10	2025	

Facility	Monteocha Park	Date <u>5/29/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department <u>ACFM</u>

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Left Restroom Flush Control	Flush control is located on the closed side of the water closet, should be on the open side.	Move flush control so that it is located on the open side of the water closet.	Carl Johns		49.09	TBD	
Restroom Toilet Paper Dispenser	Toilet paper dispensers are closer than 7" to the toilet. Should be 7-9" away from the toilet.	Move toilet paper dispensers so that they are 7-9" away from the toilet.	Carl Johns		49.08 49.16	TBD	
Right Restroom Back Grab-bar	Less than 1 ½" of clearance underneath.	Adjust grab-bar so that there is at least 1 ½" of clearance underneath.	Carl Johns		49.12	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Right Restroom Water Closet	Water closet is far from the wall, should be 16-18" from the wall.	Move water closet so that it is 16-18" from the side wall.	Carl Johns		49.15	TBD	
Right Restroom Rear Grab-bar	Rear grab-bar does not extend at least 24" on the open side of the water closet.	Adjust rear grab-bar so that it extends at least 24" on the open side of the water closet.	Carl Johns		49.01	TBD	

Facility	Veterans Memorial Park	Date _	5/8/2020
Contact Per	rson <u>Carl Johns</u>	Departme	ent <u>ACFM</u>

Email <u>fjohns@alachuacounty.us</u>

Phone 35

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion P Date	riority
Van Accessible Parking	No sign that says van accessible parking at the van accessible parking spaces.	Put a van accessible parking sign at the spaces that are van accessible.	Ed Williams	Corrected	50.20	TBD	
Women's Outdoor Restroom	Has sign with the symbol of accessibility, however there are no accessible stalls.	Remove the symbol of accessibility sign or make accommodations so that there is an accessible stall.	Carl Johns	There is an accessible restroom next to this one.	50.23 50.30	TBD	
Men and Women's Restrooms: Stall Doors	No handles on both sides of the stall doors, needs to have doors pulls on both sides.	Add handles to both sides of the stall doors.	Carl Johns		50.25 50.09	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men and Women's Grab- bars	Grab-bars are almost 37" tall, should be 33-36" from the ground.	Move grab-bars so that they are 33- 36" from the ground.	Carl Johns		50.27	TBD	
Tray Slide in Service Area	Top of tray slide is 39" tall, should be no more than 34".	Adjust tray slide so that it is no more than 34".	Carl Johns		50.32	TBD	

Facility	Owen-Illinois Park	Date <u>5/19/2020</u>	
Contact Pe	rson <u>Carl Johns</u>	Department ACFM	

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Left and Right Accessible Restroom Sinks	Sink only has 26.5" of clearance underneath, should have at least 27" of clearance for knee space.	Move sink so that there is at least 27" of clearance underneath.	Carl Johns		51.01 51.10	TBD	
Left and Right Restrooms: Rear Grab-bars	Rear grab-bars do not have at least 1 ½" of clearance underneath.	Adjust grab-bars so that there is at least 1 ½" of clearance underneath.	Carl Johns		51.02 51.11	TBD	
Left Restroom Flush Control	Flush control is on the closed side of the water closet, should be on the open side.	Move flush control to the open side of the water closet.	Carl Johns		51.02	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Left and Right Restroom Thresholds	Thresholds are ½" tall and not beveled, should be no more than ¼" or beveled to remove any safety hazards.	Adjust thresholds so that they are only ¼" tall or ½" tall with the top ¼" beveled no steeper than 1:2	Carl Johns		51.03 51.04	TBD	
Left and Right Restrooms: Soap Dispensers	Soap dispensers are mounted at 53" above the ground, should be no more than 48" from the bottom to the ground.	Move soap dispensers so that the bottom is no more than 48" from the ground.	Carl Johns		51.08 51.09	TBD	
Left and Right Restroom Signs	Signs do not have raised characters or braille, and are not mounted on the latch side of the door.	Replace signs with ones that have raised characters and braille and are located on the latch side of the door.	Carl Johns		51.06 51.07	TBD	

Facility	Poe Springs	Date <u>5/28/2020</u>
Contact Pe	rson <u>Carl Johns</u>	Department ACFM

Email <u>fjohns@alachuacounty.us</u>

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Accessible Parking	Accessible Parking Signs 38" tall.	Replace with 60" tall sign.	Carl Johns		52.01 52.02 52.03 52.23	TBD	
Front Women's Restroom Door	Closes in less than 5 seconds. Gets stuck in door frame. Requires more than 5lbs force to open.		Carl Johns		52.10	TBD	
Front Women's Restroom Sign	Sign doesn't have raised characters and braille. Isn't mounted on wall, latch side. Not marked as accessible restroom.	Replace sign that indicated restroom is accessible.	Carl Johns		52.10	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Front Women's Restroom Paper Towel Dispenser	Mounted 52" above the ground.	Move to 48".	Carl Johns		52.11	TBD	
Front Women's Restroom Accessible Stall Mirror	Mounted 52" above ground.	Replace mirror/soap dispenser combo with mirror. Mount 40" above ground.	Carl Johns	Mirror and old soap dispenser are one unit built into wall.	52.13 52.49 52.50	TBD	
Front Women's Restroom Accessible Stall Door	Doesn't have handles on both sides. Not self- closing.	Install Handles on both sides of stall door. Install stall door closer.	Carl Johns		52.12	TBD	
Front Women's Restroom Accessible Water Closet	Flush control is on the closed side.	Replace with flush control on right- side.	Carl Johns		52.13	TBD	
Front Women's Restroom Toilet Paper Dispenser	Mounted even with front of water closet.	Move 7-9" forward of water closet.	Carl Johns	Is blocking 12" clearance above side grab bar.	52.13	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Front Women's Restroom Rear Grab-bar	No rear grab bar.	Install rear grab bar.	Carl Johns		52.13	TBD	
Front Women's Restroom Side Grab-bar	26" long. Doesn't have 12" clearance above.	Replace with 42" bar. Move toilet paper dispenser.	Carl Johns		52.13	TBD	
Front Women's Restroom Accessible Sink	Pipes under sink are not insulated.	Install insulation.	Carl Johns		52.81	TBD	
Front Men's Restroom Sign	Sign doesn't have raised characters and braille. Isn't mounted on wall, latch side. Not marked as accessible restroom.	Replace sign that indicated restroom is accessible.	Carl Johns		52.14	TBD	
Front Men's Restroom Door	Closes faster than 5 seconds. Gets stuck in frame. Requires more than 5lbs of force to open.		Carl Johns		52.14	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Front Restroom Accessible Stall Door	Doesn't have handles on both sides. Not self- closing.	Install handles on both sides of stall door. Install stall door closer.	Carl Johns		52.15	TBD	
Men's Front Restroom Toilet Paper Dispenser	Mounted even with front of water closet.	Move to 7-9" in front of water closet.	Carl Johns	Is blocking 12" clearance above side grab bar.	52.16	TBD	
Men's Front Restroom Paper Towel Dispenser	Mounted 52" above ground.	Move to 48"	Carl Johns		52.17	TBD	
Men's Front Restroom Soap Dispenser	Mounted 46" above ground, over sink.	Move to side of sink over open ground, 48" max.	Carl Johns	Is blocking mirror.	52.21	TBD	
Men's Front Restroom Sink	Pipes under sink are not insulated.	Install insulation.	Carl Johns		52.20	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Men's Front Restroom Side Grab Bar	Bar is 26" long. Doesn't have 12" clearance above.	Replace with 42" grab bar. Move toilet paper dispenser.	Carl Johns		52.16 52.18 52.19	TBD	
Men's Front Restroom Rear Grab Bar	No rear grab bar.	Install rear grab bar.	Carl Johns		52.16	TBD	
Men's Front Restroom Accessible Stall Mirror	No mirror in accessible stall.	Install mirror at 40" above ground.	Carl Johns	Soap dispenser must be moved first.	52.48	TBD	
Lodge Restroom 1 Door	Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		52.33	TBD	
Lodge Restroom 1 Sign	Doesn't have raised characters or braille. Mounted on door. Not marked as accessible.	Replace sign. Mark as accessible. Mount on wall, latch side of door.	Carl Johns		52.33	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Lodge Restroom 1 Side Grab Bar	25" long. Farther than 12" from back wall.	Replace with 42" bar, mount 12" from rear wall.	Carl Johns	Must move toilet paper dispenser first.	52.24 52.25	TBD	
Lodge Restroom 1 Rear Grab Bar	No rear grab bar.	Install rear grab bar.	Carl Johns		52.24	TBD	
Lodge Restroom 1 Toilet Paper Dispenser	Mounted behind front of water closet.	Move to 7-9" forward of water closet.	Carl Johns		52.24	TBD	
Lodge Restroom 1 Paper Towel Dispenser	Mounted 51" above ground.	Move to 48".	Carl Johns		52.26	TBD	
Lodge Restroom 1 Soap Dispenser	Mounted 49" above ground, over sink.	Move to 44".	Carl Johns		52.27	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Lodge Restroom 1 Sink	Requires gripping and twisting to operate.	Replace faucet.	Carl Johns		52.28	TBD	
Lodge Restroom 2 Sign	Doesn't have raised characters or braille. Mounted on door. Not marked as accessible.	Replace sign. Mount on wall, latch side. Mark as accessible.	Carl Johns		52.32	TBD	
Lodge Restroom 2 Paper Towel Dispenser	Mounted 51" above ground.	Move to 48".	Carl Johns		52.31	TBD	
Lodge Restroom 2 Soap Dispenser	Mounted 51" above ground.	Move to 48".	Carl Johns		52.31	TBD	
Lodge Restroom 2 Toilet Paper Dispenser	Mounted farther than 9" forward of water closet.	Move to 7-9" forward of water closet.	Carl Johns		52.30	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Lodge Restroom 2 Rear Grab Bar	No rear grab bar.	Install rear grab bar.	Carl Johns		52.30	TBD	
Lodge Restroom 2 Side Grab Bar	Bar is 25" long.	Replace with 42" bar.	Carl Johns	Not be enough room to mount 42" bar. Closet door in way.	52.30 52.82	TBD	
Lodge Multipurpose Room Door	Closes faster than 5 seconds.	Adjust or replace door closer.	Carl Johns		52.34	TBD	
Gatehouse Restroom Paper Towel Dispenser	Mounted 54" above ground.	Move to 48".	Carl Johns		52.39	TBD	
Gatehouse Restroom Toilet Paper	Located on wall behind toilet.		Carl Johns	Would require remodeling. Not enough space to move 7-9" in front of water closet.	52.36 52.41	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Gatehouse Restroom Light Switch	Mounted 48.5″ above ground.	Move to 48".	Carl Johns		52.35	TBD	
Gatehouse Restroom Rear Grab Bar	No rear grab bar.		Carl Johns	Installing grab bar would require moving toilet paper.	52.36	TBD	
Gatehouse Restroom Side Grab Bar	Bar is 26" long.		Carl Johns	Not enough room for 42" bar.	52.36 52.37	TBD	
Gatehouse Restroom Water Closet	Mounted 14" from side wall.	Move so centerline of water closet is 16-18" from side wall.	Carl Johns		52.38	TBD	
Gatehouse Restroom Sink	Pipes underneath are not insulated.	Install insulation.	Carl Johns		52.40	TBD	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Gatehouse Restroom	Not enough maneuvering space.		Carl Johns	Requires remodeling gatehouse.	52.36 52.41	TBD	
Lodge Water Fountain	Faucet 9.5" from rear wall. No clear space underneath.	Replace water fountain.	Carl Johns		52.06 52.42 52.43	TBD	
Snack Shack East Water Fountain	Faucet 9" from rear wall and 41" from ground. No clear space underneath.	Replace water fountain. Lower so faucet is 36".	Carl Johns		52.07 52.58	TBD	
Pavilions 1, 2, 3, 4	No accessible path to pavilions.	Create accessible pathways to pavilions.	Ed Williams	Path distances: Pav1: 21ft Pav2: 175ft Pav3: 100ft Pav4: 65ft Sidewalk added to building #1	52.04 52.05 52.08 52.09	TBD	
Restrooms Next to Spring Path	No accessible path to restrooms.	Create accessible path to restrooms.	Ed Williams	Restroom replacement project underway (in bidding phase)	52.75 52.76 52.77 52.78 52.79 52.80	2025	

Area	Access Issue	Solution	Person Responsible	Comments	Photo	Target Completion Date	Priority
Restrooms Next to Springs Signs	No signs directing toward accessible restrooms.	Install directional signs.	Ed Williams	Rear restrooms near spring are non- accessible. Restroom replacement project underway (in bidding phase)	52.75 52.76	2025	